
AD-A156 959	CAREER I REALIGNI CARLISLI	MANAGEMENT F MENT A MAJOR E BARRACKS P	IELD 67-AV1	ATION MAINTEN RDIU) ARMY WAI ARD 15 APR 85	ANCE R COLL	1/1	`
UNCLASSIFIED					F/G 5/9	NL	
	<b>%</b> .						
				<del>-  </del>			
							<del>                                     </del>
							يكبل



AD-A156 959



SECURITY CLASSIFICATION OF THIS PAGE (When Date Entered) UNCLASSIFIED					
REPORT DOCUMENTATION	PAGE	READ INSTRUCTIONS BEFORE COMPLETING FORM			
1. REPORT HUMBER	2. GOVT ACCESSION NO.	3. RECIPIENT'S CATALOG NUMBER			
	AD - A156 959				
4. TITLE (and Subtitio)	1111	S. TYPE OF REPORT & PERIOD COVERED			
"Career Management Field 67Avia					
Maintenance Realignment A Major S	tep Forward"	STUDENT ESSAY			
		6. PERFORMING ORG. REPORT NUMBER			
[					
7. AUTHOR(e)		8. CONTRACT OR GRANT NUMBER(*)			
LTC(P) Charles N. Bullard					
-		-			
9. PERFORMING ORGANIZATION NAME AND ADDRESS		10 SPOCEAN EL EMENT DECLECT TACK			
US Army War College	•	10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS			
Carlisle Barracks, PA 17013-5050					
11. CONTROLLING OFFICE NAME AND ADDRESS		12. REPORT DATE			
		15 April 1985			
Same		13. NUMBER OF PAGES			
<u> </u>		119			
14. MONITORING AGENCY NAME & ADDRESS(If differen	nt from Controlling Office)	15. SECURITY CLASS. (of this report)			
1		IDIOT AGGT STED			
		UNCLASSIFIED			
		154. DECLASSIFICATION/DOWNGRADING SCHEDULE			
16. DISTRIBUTION STATEMENT (of this Report)					
is spiritor or a calant (or and repair)					
Approved for public release; dist	ribution unlimite	ed.			
,					
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)					
<u>.</u>					
18. SUPPLEMENTARY NOTES					
19. KEY WORDS (Continue on reverse side if necessary a	nd identify by block number	· · · · · · · · · · · · · · · · · · ·			
İ					
1					
20. ABSTRACT (Continue on reverse side if necessary a		OA)			
In 1979, the Chief of Staff of the US Army (CSA) made the decision to realign Career Management Field 67, Enlisted Aviation Maintenance (CMF 67) due					
to problems in morale, maintenance standards, training deficiencies and other					
major problems within the enlisted aviation community. These problems were					
havi- a severe impact on retention of qualified aviation maintenance personnel					
and it was apparent that something had to be done to "fix" the system. When					
fully implemented, the realignment					
1,	-,				

DD 1 JAN 73 1473 EDITION OF 1 NOV 65 IS OBSOLETE

UNCLASSIFIED

(See continuation)

MECURITY CLASSIFICATION OF THIS PACE/Then Date Entered

# 20. ASSTRACT--Continuation.

soldiers within the enlisted aviation career field. The study leading up to this decision and the problems encountered in implementing the CSA guidance along with lessons learned and recommendations for future realignments will be the main thrust of this essay.

This essay, by use of the historical method of research, provides the history of CMF 67 prior to the restructure as well as the problems encountered during each major phase of the realignment.

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE(When Date Entered)

The views expressed in this paper are those of the author and do not necessarily reflect the views of the Department of Defense or any of its agencies. This document may not be released for open publication until it has been cleared by the appropriate military service or government agency.

USAWC MILITARY STUDIES PROGRAM

# CAREER MANAGEMENT FIELD 67-AVIATION MAINTENANCE REALIGNMENT A MAJOR STEP FORWARD

AN INDIVIDUAL ESSAY PROJECT

Ъγ

Lieutenant Colonel (P) Charles N. Bullard (Author)

Colonel Frank Alexander, ADA Project Advisor

Accession For	7
NTIS GRAAL DTIC TAB Unannounced	
tribution/	
Availability  Avail and Dist   Special	d/or
A-2	

US Army War College arlisle Barracks, Pennsylvania 17013 15 April 1985

> DISTRIBUTION STATEMENT A: Approved for public release; distribution is unlimited.

> > The state of the s

1.11

#### **ABSTRACT**

AUTHOR: Charles N. Bullard, LTC (P), TC

TITLE: Career Management Field 67-Aviation Maintenance Realignment A Major Step Forward

FORMAT: Individual Essay Project

15 April 1985 PAGES CLASSIFICATION: Unclassified

In 1979, the Chief of Staff of the US Army (CSA) made the decision to realign Career Management Field 67, Enlisted Aviation Maintenance (CMF 67) due to problems in morale, maintenance standards, training deficiencies and other major problems within the enlisted aviation community. problems were having a severe impact on retention of qualified aviation maintenance personnel and it was apparent that something had to be done to grafix the system. When fully implemented, the realignment/restructure would affect over 2500 enlisted soldiers within the enlisted aviation career field. The study leading up to this decision and the problems encountered in implementing the CSA guidance along with lessons learned and recommendations realignments will be the main thrust of this essay.

This essay, by use of the historical method of research, provides the history of CMF 67 prior to the restructure as well as the problems encountered during each major phase of

our oft maintenance it is a small of

## HISTORY AND PLANNING PHASE

Keeping today's wide variety of sophisticated Army aircraft flying has always been a demanding job. Soldiers who have this responsibility must be familiar with a vast array of mechanical, electrical, and hydraulic systems. As new aircraft such as the UH 60, CH 47D, and the AH 64 are introduced into the inventory, the demands on the aviation maintenance soldier increase dramatically.

In 1979, the Department of the Army, after realizing that the quality of aviation maintenance was losing ground, directed that the Army Aviation Maintenance Career Management Field 67 be studied. Under the sponsorship of Mr. Joe Cribbins of the Deputy Chief of Staff Logistics office, the study conducted a detailed evaluation of the 17 aircraft repair and aircraft component repair military occupational specialties (MOS) which constituted the enlisted Aviation Maintenance Field (CMF) 67. The study concluded that the apparent decline in Army aviation maintenance effectiveness could be attributed to:2

- 1. An inadequate organizational structure.
- 2. An ineffective MOS structure.
- 3. Inappropriate grade authorizations.
- 4. Unsatisfactory retention rates.
- 5. Less than effective training programs.
- 6. Increased equipment complexity.

page 1

The above study produced approximately 76 findings and 48 recommendations pertaining to the above problem areas. The Vice Chief of Staff of the Army (VCSA) was briefed on this study on 29 September 1980 at which time he agreed to the findings and directed the Training and Doctrine Command to assess these findings and develop an implementation plan. The US Army Transportation School ( now the US Army Aviation Logistics Center) as proponent was tasked to develop the plan which was briefed to and approved by the VCSA on 23 February 1981. The plan, which recognized the critical interrelationship between force structure, training, personnel management and unit mission was designed to accomplish the following: 4

- 1. Revise the CMF 67 MOS structure from 17 MOS grouped in two subfields to 30 MOS divided into six subfields. The approved new CMF 67 structure and the structure as it was at that time is shown at Appendix A and B.
- 2. Revise appropriate Army regulations to implement the new CMF 67 MOS structure.
- 3. Develop a plan for reclassification and transition to the new CMF 67 MOS structure.
- 4. Develop comprehensive aviation maintenance training courses and literature to support each MOS in the revised CMF 67 MOS structure.
  - 5. Review Aviation MACRIT data collected by the Sample

Data Collection Program to determine appropriate MOS, grades, skill levels, and density for staffing organizations using the revised CMF 67 MOS structure.

- 6. Review all enlisted aviation maintenance positions in the Army and coordinate with MACOMS, ARSTAF, and MILPERCEN to recode the positions in accordance with the revised CMF 67 MOS structure to include coding positions with appropriate SQIs and/or ASIs. The resultant structure should permit retaining crew chiefs with a designated aircraft system by mission design series aircraft through grade E-6. Further, the structure must provide adequate aviation maintenance personnel in the correct MOS, skill level, and grade to maintain a high state of aviation readiness. The structure must be grade feasible, sustainable, and offer adequate career progression opportunity to retain experienced personnel.
- 7. Review the CMF 67 Study findings on non-aviator flying status for enlisted personnel and incentives for retention in CMF 67 and determine what changes in administration of enlisted flight pay and other monetary incentives are required to retain experienced aviation mechanics/crew chiefs. Monetary incentives are needed to retain nonflying crew chiefs in these vital jobs. (This subject will not be discussed in this essay.)
- 8. Review the number and grades of non-CMF 67 soldiers reenlisting for CMF 67 and determine what restrictions should be placed on the total number and grade of non-CMF 67 soldiers that

are permitted to reenlist for CMF 67. (CMF 67 has since been closed to all non-CMF 67 personnel unless approved by MILPERCEN).

9. Review CMF 67 Study findings on aero scout observers and helicopter door gunners and determine what changes in Army policies are required to be made.

The above plan which got underway in ernest in early 1982 was originally scheduled for final implementation on 1 April 1984 and was designed to:

- Restructure CMF 67 to provide technical inspectors for each aircraft type.
- Provide a technically qualified E-7 supervisor for a two aircraft family.
  - 3. Improve supervision and career progression.
- 4. Revise AIT to train "doer" and not assistant repairer.
  - 5. Revise training for SL 30/40 supervisors.
  - 6. Provide training for technical inspectors.

The realignment required the deletion of 3 MOS: 67W (Aircraft Quality Control Supervisor), 67240 (Aircraft Maintenance Senior Sergeant), and 68M30 (Aircraft Weapons Systems Repairer). Other major changes included the addition of 13 new MOS, the majority of which were in the new 66 series MOS, Technical Inspector. In addition, approximately 2500

reclassification actions were required to be completed during the revision of CMF 67. Revised MOS specification recalssification guidance was published by letter of notification and was included in Change 20 to AR 611-201. See Appendix C for a list of the new MOS. In order to effect a smooth transition to the new MOS structure, the reclassification effort was centralized at DA MILPERCEN level with proponent representatives from the US Army Aviation Logistics Center, Ft Eustis, Va providing assistance in the actual review of individual reclassification actions. Included in the reclassification packet was a completed survey/questionaire which was provided to and completed by each soldier. This survey was a great asset during the reclassification effort in that it provided the soldier's past experience, Commander's/First Sergeant's recommendation and the soldier's desires. These factors were matched against the needs of the Army after the realignment authorizations were considered and a decision was then made as to what MOS a particular soldier was awarded. The reclassification effort will be discussed more in detail later in this essay.

The realignment of CMF 67 was designed to greatly enhance the overall efficiency of aviation maintenance. When fully implemented it will produce better career opportunities for career progression, schooling, promotion, and personal satisfaction for the enlisted soldiers who serve in Army

aviation. The remainder of this essay will be devoted to a more detailed discussion of the above realignment followed by lessons learned and recommendations for future realignments of this magnitude. Because this essay has two objectives; to give recommendations for future revisions and to serve as a historical document for the CMF 67 realignment, I have included numerous historical documents such as messages and memos for future use as required.

#### MILESTONES

The CMF 67 realignment was not something that could be accomplished overnight. In an effort to control this revision and to track the major actions involved, a milestone chart was formulated and followed as much as possible. While the majority of these milestones were met with only minor problems some proved to be major obstacles, the most serious being that of documenting the new MOS in the MTOE/TDA in the field. Problems associated with documenting the CMF 67 realignment will be discussed in further detail later in this essay. A copy of the original MILESTONES is attached at Appendix D.

# EDUCATING THE FIELD

In order to "advertise" this major aviation revision a team comprised of members of the Transportation/Aviation Branch, Enlisted Personnel Management Directorate, MILPERCEN, Alexandria, VA., and the US Army Aviation Logistics Center (USAALC), Ft.

Eustis, Va., conducted world-wide briefings during the period September 1982 through June 1983. This team of "experts" visited all major installations on two occasions, conducting briefings to the staff and all aviation soldiers. In addition, they left blank survey questionaires for completion by each soldier affected by the revision. This survey would prove to be an invaluable asset in determining exactly what military occupational Specialty (MOS) to award those soldiers who were required to change MOS's under the new alignment. On the second visit, this team collected the completed surveys and conducted on-site interviews with the affected soldiers. These one on one briefings and personal interviews proved to be highly successful due to the fact that the soldiers affected felt that the realignment must be important or "HQS DA" or "my assignment branch" would not have sent their representatives. In any event the world-wide briefing tour was deemed a success because it added creditility to the proposed realignment. A copy of the triefing presented during these visits is attached at Appendix E.

## TRAINING

During the early stages of the CMF 67 realignment study, it was determined that there would be a requirement to train to Army standards approximately 1500 soldiers during FY 84 and FY 85 to meet the initial Army requirements for qualified Aircraft Technical Inspectors, the new 66 series MOS. The CMF 67 realignment plan included the documentation of this new MOS which

planning put into this action that the realignment of the enlisted aviation CMF will produce better career opportunities for schooling, promotion, and personal satisfaction for the soldiers who serve in Army Aviation.

adhered to. Our force development people in the field can only do so much.

- 5. Insure that SSC-MCR review all Consolidated TOE Updates (CTU) prior to release by TRADOC to insure that the Standards Of Grade (SGA) is uniform and accurate. This review proved to be invaluable during the CMF 67 realignment. TOE development, to include application of SGA must provide an accurate design model for use in the MTOE documentation process. 7
- 6. Improvement must be made in the quality and content of Letters of Notification, DA Circulars and Army Regulations.
- 7. All changes must include thorough coordination with the National Guard and Reserve Components.
- 8. Continue to schedule pre-moc window" briefings by SSC-NCR on the changes slated for each MOC window. This will afford each MACOM the opportunity to review programmed changes prior to execution.
- 9. Provide on-site visits of representatives from the DA level responsible for monitoring realignments.
- 10. Insure that adequate "safety measures" are incorporated in all MILESTONE time charts to insure that documentation is correct prior to any major reclassification action.

It is quite evident that the realignment of CMF 67 was handled in a manner so as not to duplicate past mistakes during similar actions. I am confident that because of the effort and

planners who were involved because it is quite evident that all their long tedious hours of "stubby pencil" work has paid off.

It would be difficult to undergo a realignment of this nature without learning something and this action was no exception. In this regard I will close this essay with the following recommendations:

- 1. Reclassification authority should continue to be centralized at the DA MILPERCEN level to preclude reclassification actions in the field based on personalities and not on the soldiers experience and the needs of the Army.
- 2. The ODCSOPS must put more "teeth" into their system for requiring MACOMS to change MTOE/TDA. It appears that under the present system, MACOMS change those areas that they want to change or those that they can afford to change rather than change those that they have been directed.
- 3. A review of all major changes of this magnitude must be made prior to allowing these changes into the "system" at ODCSOPS. This will preclude letting unauthorized changes into the system.
- 4. The number of force development trained officers and NCO'S must be reviewed for possible increased authorizations. Many problems encountered during this realignment were due to a shortage of qualified people to make the required changes. This is especially crucial when the MACOMS get so many changes "dumped" on them from all levels. Priorities must be set up and

deemed a "success" because of this follow up action by all concerned.

A recent review of the authorizations within CMF 67 reveal that the overall strength across all grades was at the 105% level and was scheduled to be at approximately 103% by June 1985. A closer look shows that the overall authorizations at the E-5 level had dropped from 5289 prior to the realignment down to 4153 in June 1985. When the final authorization for E-5's reaches the 3800 area the new alignment goals for that grade will be reached and the excess authorizations and the problems associated with that excess will be alleviated. Coordination with DA MILPERCEN in March 1935 revealed that they are closely monitoring the reclassification action and authorizations within CMF 67 to preclude the occurance of any unmanageable problems.

# SUMMARY AND RECOMMENDATIONS

The realignment of CMF 67 was a major undertaking. Planning was initiated in 1979 and before the actual plan was implemented over five years had passed. During these five years there were thousands of man-hours expended by all concerned to insure a smooth transition from one structure to another. The task of these Army planners was to take the Aviation CMF and almost double it and to do so with no plus ups in authorizations. In addition, they were directed to establish a training program for the new aviation MOS and to set up better training at the Advanced Individual Training level. My hat is off to those

7

the Army were reminded by message that in accordance with Appendix A, DA Circular 611-83-1, each installation would be provided a by-name listing for DA MILPERCEN in June 1984 of personnel to be reclassified. Detailed reclassification instructions were also provided with each list along with guidance that stated that no Aviation Maintenance soldier would be reclassified under this effort until such time as the "official" list was released at DA MILPERCEN. The only exception to this policy was for soldiers who were currently attending the MOS 66 Technical Inspector course at FT Eustis. These soldiers were awarded the appropriate 66 series MOS by the USAALC upon completion of the required training.6 In addition, enlisted soldiers who were enroute to new assignments on 1 July 1984 were instructed to continue according to their original assignment instructions. A by-name listing of all soldiers in a Permanent Change of Station status was provided each gaining installation for use in their planning and for reclassification of these soldiers after their arrival.

The initial MACOM reclassification documentaion for the July 84 MOC window contained numerous errors of various degrees with approximately 400 such errors noted. However, after a review by MILPERCEN and subsequent guidance to the field, the errors were corrected on a case by case basis with approximately 25 reclassification actions remaining to be completed by the end of March 1985. The CMF 67 reclassification action was officially

Elton's decision to implement the reclassification of almost 2600 aviation soldiers meant that the planning which had begun in 1979 would finally be officially "laid in concrete".

Upon implementing the reclassification actions on 1 July 1984, it was discovered that while the MACOM documentation was better some errors still existed. However, this was anticipated prior to the actual implementation and because of the off-line systems mentioned before EPMD was able to monitor the problem areas and "fix" them as time permitted. While the Army needs to get away from having to manage off-line, in this instance it was the only alternative available without further delaying the long awaited reclassification for the third time.

As a point of interest this reclassification action also included changes for CMF 63 Power Generator Operators which were to be accomplished along with the CMF 67 actions. While this essay did not address the problems associated with this action, it should be noted that the requirement to submit these changes along with the aviation reclassifications compounded the problems encountered throughout the realignment due to the magnitude of required changes. A summary of the CMF 63 changes is attached at Appendix N.

# IMPLEMENTATION PHASE

As previously stated, the reclassification action affecting in excess of 2500 aviation soldiers was officially implemented on 1 July 1984. Prior to this date personnel officers throughout

Due to the substantial errors and omissions which continued to exist in MACOM documentation, the DCSPER, LTG Elton made the decision to delay the reclassification of aviation soldiers under this realingment from 1 April 1984 to 1 July 1984 with one additional documentation scrub planned for May 1984. A copy of the message announcing this change is attached at Appendix L. In this message LTG Elton encouraged MACOM Commanders to work closely with their force development people in a combined effort to solve this problem.

In an additional effort to "fix" the above documentation problems prior to the reclassification action a documentation team from the Soldiers Support Center visted the MACOMS once again beginning in January 1984 to assist their documentors in identifying problems and to provide any guidance possible. The next input which was due to arrive in Washington for the July 84 MOC window was reviewed during these visits. This visit coupled with the past efforts at identifying documentation problems finally paid dividends because when a pre-scrub of MACOM input was reviewed again in May 1984 the error rate had improved substantially. The actual MACOM CMF 67 documentation error rate is attached at Appendix M. Due to this drastic improvement in documentation, the DCSPER made the final decision to go ahead with the 1 July 1984 CMF 67 reclassification action as planned. Up to this point all actions had been in the planning stages only, with no official changes made to existing MTOE/TDA. LTG (MOC) window. This was made possible by a decision by ODCSOPS to accept these changes as "Proponent Approved" which speeded up the process considerably. Another re-scrub of these most recent changes was scheduled for 20 December 1983 at which time another go; no-go decision would be made as to whether or not to go ahead with the reclassification of the almost 2600 aviation soldiers. These documentation scrubs and the problems leading up to them were briefed to the DCSPER of the Army on 12 December 1983. Copies of charts used during this briefing are attached as Appendix J. Other correspondence dealing with these problems is included for historical purposes at Appendix K.

During January 1984, the input which resulted from the November 83 re-scrub was again reviewed by SSC-NCR and the Aviation Logistics Center. This review revealed that although the documentation had improved, there were still significant errors noted, especially in the Standard Of Grade area. More specifically, the majority of the problems involved regrading positions in the MTOE/TDA to bring the grade spread into line with approved Standards Of Grade; reclassification from one MOS to another on a one-on-one basis; or the retitling of a position for clearer indentification. In some instances MACOMS made changes that were outside the levels for which their units were resourced. The guidance from the beginning was to make all changes within current levels of authorizations with no plus ups authorized.

4. Skill level 40 capper MOS not documented or not documented properly.

In an attempt to expeditiously correct the documentation deficiencies, the USAALC and MILPERCEN supported by the Soldiers Support Center, NCR hosted a conference to "fix" the documentation. MACOMS were requested to send qualified representatives to participate in a scrub of all MTOE/TDA and to correct the errors. This conference was held on 14 November 1983 in Washington D. C. Since all documents were required to be before the reclassification actions could implemented, each MACOM was asked to participate with their best force development personnel. During this scrub each document was reviewed using the most recent MACRIT chart to determine the required grades for each aviation unit. If accomplished properly this procedure would insure a proper grade distribution within each unit, thereby eliminating the excess at the E-5 level.

Upon completion of the above re-scrub of documentation on or about 16 November 1983 the MACOM representatives were requested to return to their respective commands, make the required changes and resubmit these changes by 30 November 1983. This was almost a "mission impossible" due to the sheer magnitude of changes required and shortage of qualified force development personnel. Despite these momumental problems, the larger MACOMS such as Forces Command, Europe and Korea were able to submit their changes in time to make the 30 November mini management of change

aviation realignment was designed to alleviate this problem.

In an effort to insure proper documentation throughout the field, item number nineteen of the milestones required that the Soldiers Support Center, National Capital Region, in Alexandria, Va. review all CMF 67 documentation changes submitted by the Major Commands (MACOM). The first documentation review was scheduled for 1-30 November 1983. The decision was made early on to delay the major reclassification effort if in fact the documentation changes submitted from the field were not correct. This decision was to pay dividends later due to the fact that the initial effort from the field to document the CMF 67 changes left much to be desired. During the initial review of MACOM documentation in early November 1983, errors/cmissions in application of the CMF 67 restructure guidance specified in change 20, AR 611-201 were identified. These errors included:

- 1. Revised Standard of Grade Authorizations (SGA) were not applied correctly. Most MACOMS did not change the authorizations for E-5's as directed. If allowed this would have resulted in a continuation of the grade infeasibility (excess E-5) problem.
- 2. Technical Inspectors (New MOS 66 series) not documented or documented incorrectly.
- 3. Technical Inspector positions documented where not authorized. (MOS 66 series).

board in that it provided the soldiers past experience, the Commanders and First Sergeamts recommendations as well as the soldiers desires. These factors were matched against the needs of the Army after the realignment authorizations were considered and then a decision was made as to what MOS a particular soldier was awarded. Each soldier was notified of the boards decision by a personal letter signed by his assignment Branch Chief. See Appendix H for more detailed information in this area.

#### DOCUMENTING THE REALIGNMENT

As anticipated during the planning stages of the revision, documentation of the required changes proved to be the most critical of all required actions. One of the purposes of the realignment was to provide a feasible Career Management Field space and grade structure. Prior to the decision to realign, the inventory of soldiers at the E-5 level in CMF 67 was severely short when compared to actual E-5 authorizations. See Appendix 1. Aviation soldiers could advance to the grade of E-5 very rapidly. However, this rapid advancement resulted in an excess of E-5's and these soldiers would stagnate at that level with little or no chance of advancing to E-6. This resulted in a desire to migrate out of aviation into an MOS in which the soldier could be promoted to E-6. After promotion to E-6 some soldiers were allowed back into aviation. This time lag between reclassifications in some cases resulted in a deterioration of aviation maintenance skills. Proper documentation under the

armament repair personnel now remain in their respective subfields until they are promoted to E8.

During the planning stages of this realignment the decision was made to centralize the reclassification at the DA level to insure that the right soldier was placed in the right MOS. Past experience has proven that when a reclassification action of this magnitude is accomplished in the field, many times the field units document what they "want", not necessarily what they are authorized. As a result of this decision a message from EPMD, MILPERCEN was dispatched to the MACOMS in December 1982 announcing this centralization. The original plan called for the reclassification action to be implemented on 1 October 1983. This date was subsquently changed to 1 April 1984 and again to 1 July 1984. The reasons for these changes are discussed in the next section of this essay.

In order to accomplish the above centralized reclassification effort it was necessary to form a board that would meet in Washington, D.C. to review the records of all those aviation soldiers eligible for reclassification. This board was comprised of personnel from the USAALC and EPMD who were required to review a reclassification packet on each affected soldier. Included in this packet was an updated micro-fiche of each. soldiers personnel file and a completed survey/questionaire which was provided to the soldier during the world-wide briefing tour. This survey proved to be invaluable during the conduct of this

identified and coordinated with on a case by case basis. School no-shows is an Army wide problem and requires constant monitoring and team work to eliminate.

Prior to the above training the non-commissioned officers working in the Aviation section of the Transportation/Aviation Branch formulated an outstanding off-line management system to track those soldiers who were identified to attend training prior to the actual award of the new MOS. Without this off-line tracking system it would have been virtually impossible to meet the required training under the realignment, especially when faced with the no-show problem which cropped up later on.

## THE RECLASSIFICATION EFFORT

As mentioned earlier, the CMF 67 realignment required a major reclassification which would affect almost 2600 enlisted aviation soldiers. The majority of the reclassification effort was centered around the new 66 Technical Inspector series MOS. For example, a staff sergeant, MOS 67W30, Aircraft Quality Control Supervisor, with the majority of his/her experience in Utility/Cargo Airplanes would be reclassified to 66G30, Utility/Cargo Airplane Technical Inspector. This precluded personnel with only fixed wing aircraft maintenance experience through grade E6 being assigned as helicopter platoon sergeants or helicopter maintenance supervisors as E7's. A simular condition existed with aircraft component repair supervisors, however, under the new realignment, fixed and rotary wing

would make this training requirement "official". Personnel were selected for training to meet these new MOS requirements by a DA selection board made up of aviation qualified personnel from the USAALC and EPMD, MILPERCEN. The training program was established to allow for completion of all required MOS 66 training to fill the new authorizatons by the end of FY 85. In order to accomplish this mission the Transportation/Aviation Branch, EPMD, MILPERCEN was required to identify and train qualified personnel on a temporary duty (TDY) enroute basis. TDY enroute was necessary in the beginning because MACOMS had not funded sufficiently to send soldiers TDY and return. In an effort to alleviate this training money problem a request for DA funding was sent to ODCSOPS on 2 December 1983. In addition, a message was dispatched from EPMD to all MACOMS asking for their assistance in making maximum use of TDY and return monies. Appendix F and G. Although some training was delayed for the initial lack of qualified instructor personnel and availability of training aids, the initial 66 series MOS training got underway in May 1984. The major problem that has been surfaced since this training began is the problem of soldier no-shows which results in lost training seats and stretches out the time required to complete the training of required personnel. In an effort to alleviate this problem EPMD MILPERCEN has sent message traffic to installations concerned requesting their assistance. In addition, those MACOMS with the bulk of school no-shows are being

# ENDNOTES

- 1. Letter, DA, US Army Transportation School, subject Army Aviation Career Management Field (CMF) 67, dated 2 April 1982.
- 2. Ibid.
- 3. Ibid.
- 4. Ibid.
- 5. Information Paper, DAPC-EPL-TA, subject <u>Career Management Field 67.</u> <u>Aviation Maintenance MOS Realignment</u>, dated 1 June 1984.
- 6. Ibid.
- 7. Message, SSO, DA, DCSPER, subject <u>Delay of Personnel</u> <u>Reclassification in CMF 67 and CMF 63</u>, dated 21 March 1984.

APPENDIX A

r 🔠 MCH. 2011 7141 7141 1141 1141 --[1]

Titles de pret would be helper

A

ALLIED TRADES WOUS/refabre.	Martin sector income process (martin process control process c	
CH-S" CHUOOK	21/08 21/08 21/08 United States United State	Many Managements and the second secon
411-1 011-6 011-58 COBRA CAYUSE/Kiam	11.12. 811121 11.00 114501 11.00 114501 11.0	
435-40 BJ-44	THE	
HH-1 UN-60	ANTINION DE TOUR THE	
CIZ/UZI MOHAWK	Treit Print, Briefly Billion and Fillion Constitution and Constitution Constitution and Constitution Cons	

H 2

•

 $^{\prime} \backslash \!\! \backslash$ 

APPENDIX B

B

APPENDIX C

.

.

1 1

\_\_ A

# NEW CMF 67 MOS

66G UTILITY CARGO AIRPLANE TECH INSP OBSN AIRPLANE TECH INSP 66H UTIL HEL TECH INSP 66N TACT TRANS HEL TECH INSP 66T ATK HEL REPAIRER (AH-64 NEW A/C) 67R ATK HEL TECH INSP (AH-64 NEW A/C) 66R 67[] SCOUT HEL REPAIRER (OH-58A NEW A/C) SCOUT HEL TECH INSP (OH-58A NEW A/C) 66[] ATK HEL TECH INSP 66Y OBSN SCOUT HEL TECH INSP 667 HVY LIFT HEL TECH INSP 66X MED LIFT HEL TECH INSP 660 ACFT ARMAMENT TECH INSP 66J

APPENCIX D

,

-

\_\_\_\_\_

\_

MILESTONES

apparlix D

 $\mathbb{D}$ 

4

## DOCUMENTATION AND RECLASSIFICATION MILESTONES

	MILESTONE	LEAD AGENCY/COMMAND	<u>STATUS</u>
1.	PROPOSED RESTRUCTURING	TRADOC	COMPLETED 1 JUL 1982.
	TO SSC		
2.	MACOM STAFFING	SSC ~ NCR	COMPLETED AND APPROVED
			19 DEC 82.
3.	DA STAFFING	SSC - NCR	COMPLETED IN OCT - NOV 82
4.	DCSPER APPROVAL	DCSPER	COMPLETED. ON 20 DEC 82,
		•	DCSPER APPROVED CMF 67
			RESTRUCTURE AS A "ZERO
			SUM" RECLASSIFICATION AC-
			TION FOR FY84. ADDITIONAL
			REQT'S GENERATED BY RE-
			STRUCTURE WILL BE REVIEWED
			BY DAMO-FD AND IF VALI-
			DATED W/B RESOURCED IN NOT
			MAL POM CYLCLES.

	MILESTONE	LEAD AGENCY/COMMAND	STATUS
5.	LON PUBLISHED	SSC - NCR	COMPLETED. LON E-20-7 DATEI 13 JAN 83 PROVIDES DETAILS FOR RESTRUCTURE.
, <b>6.</b>	TRAINING SCOPE TO USAREC	TRADOC	DEPENDING UPON THE ESTABLIH- MENT OF NEW MOS FOR AH64 (67 AHIP (67S).
7.	POS EDIT TAPE PREPARED	SSC - NCR	COMPLETED AND DISTRIBUTION TO MACOMS 16 May 83. IN- CLUDES REVIEW OF 200 TOE AND 117 TDA.
8.	CH 20, TO AR 611-201 & CIRCULAR TO PRINTER	SSC - NCR	To PRINTER 24 JUNE 83,
9.	IMPLEMENTATION CIRCULAR	TAGCEN	
10.	CH 20, AR 611-201 TO FIELD	TAGCEN	SEPT 83 WITH TOTAL REWRITE  OCT/NOV 83 DUE TO PHYS STAN-  DARDS CHANGE (IE WITA)  CHANGE 1 TO BE PUBLISHED  1 MAR 84.
11.	CCT PUBLISHED	TRADOC	COMPLETED BY TRADOC. DCSOPS REVIEW NOT COMPLETE DUE TO PLUS UPS IN AUTHORIZATIONS. AFFORDABILITY STU DY BEING CONDUCTED.

	MILESTONE	LEAD AGENCY/COMMAND	STATUS
12.	POI APPROVED	TRADOC	PRESENTLY AT TRADOC PENDING OFFICIAL TRAINING APPROVAL.
13.	ARPRINT UPDATE	MILPERCEN	COMPLETED. NEW MOS ENTERED IN ARPRINT.
14.	REQUEST LOADED	MILPERCEN	DEPENDING UPON THE ESTABLISHMENT OF NEW MOS FOR AH64(67R) AHIP(67S).
15.	RECRUITING BEGINS	USAREC	WHEN NEW MOS COME ON LINE.  RECRUITING SHOULD BEGIN IN  84.
16.	TYPE B CHANGES IN TAADS	MACOMS	SCHEDULED FOR JUL - SEP 83 MOC WINDOW. DRIVEN BY CCT 300-74.

## DOCUMENTATION AND RECLASSIFICATION/MILESTONES (CONT'D)

17. PERSACS UPDATE	MILPERCEN	15 Oct 83	
18. TRAINING COMMENCES	T-School	0ст 83	FT EUSTIS MAY REQUEST DELAY.
19. REVIEW MACOM DOCU- MENTATION	SSC-NCR	1-30 Nov 83	NOTIFY MACOM(S) OF ER- RORS IN DOCUMENTATION
20. AUTHORITY TO EXE- CUTE RECLASSIFICATION	MILPERCEN	1 DEC 83	PROVIDED MACOM DOC.  IS ACCEPTED. (ACCEPTABL  DOCUMENTATION CRITICAL 1  REMAINDER OF MILESTONES)
21. PERSONNEL RECLASSI- FICATIONS COMPLETED & REPORTED THRU SIDPERS		NLT 1 APR 84	PER RECLASSIFICATION GUIDANCE CONTAINED IN LC WITH EFFECTIVE DATE 1 APR 84.
22. PERSONNEL IN MTOE/TDA UNITS RECLASSIFIED	MACOMS	Mar 84	EFFECTIVE DATE OF RE- CLASSIFICATION 1 APR 84.
23. EFFECTIVE DATE OF MTOE TDA	/	1 APR 84	
24. REQUISITIONS UNDER REALIGNMENT COMMENCE	MACOMS	1 May 84	

GB BB

UUUU

YEAR OF SOME CAMERIERCE. THE US CERTIS SCENITED WEST OF CORRESS.

IN THE TECHNICAL INSPECTION TACK FOR THE PARTICULAR SINCRAFT THAY

BETVICE. THE SULVER MUST ACREIVE THE COMPLISHED MICESSARY TO

HELFORM TECHNICAL INSPECTION ON HOUR PERFORMED BY THE ALLIED TRADES

JOS AVEBERS. THIS RECESSITATES RESIDENT TRAINING WITH HIGH TASK

JENSITY AND TRAINER SKILLS. MINIMUM COURSE LEBETH FOR THE BY

SENTIS FOR IS AS REEKS WITH A MAXIMUM OF RESIDENS.

- 3. A TRAINING PROGRAM HAD DEEN ESTABLISHED TO ALLOW FOR COMPLETION OF ACE NAMED AND SERVED POS TRAINING TO FILL BED FERCENT OF HIS ABI COLORS AND A TREE BY THE PARTY OF TO SUCCESSIONERY ACCOMPLISHMENT FLASORISE NUMBER OF SUCCESSIONERY ACCOMPLISHMENT FLASORISM ACCOMPLISHMENT FLAS
- Facility of the August State Alexander Company of the August State August August State August State August State August State August State August Augu
- Second Color of the Company and Market Company for the Color State Color of the 
UNCLASSIFIED

ઇ

(--

UL UB DOLMASE DEC 30 DR RR BULU

NOT BILLHONGON ALEX VO //UPP/-Line-1, //

40 23.75

A10 740%

A10 11577

INFO CON IST PENSCOR SCHNETZINGED DEZZZEDPE-BOD-67/

CLO MILHERCEN ALEX MANNERPORTARIANTARIONA

NOTE: AND ASSISTANCE CONTINUES OF SELECTION

UT CLAS

TALKS MESSAGE HOSEN CONTROL SY STREET HAVE

1200: Coloniano 300 be 1 10111 78% 7.0411110

As bon character with the Charlest of Energy of Millian (CCC) withhat the contraction of the CCC with the Millian was accessed to the CCC of the Millian was accessed to the CCC of the CCC

3. The restrict of the content of the ASS for a property of Terror content of the Content of

14. The contract of the property of the contract of Section Temperature.
16. Fig. 4.26.
17. The contract of t

THE COLEY REPORTS FOR A

Charles are some 1970 Enter a C Carana Processor Association

E CLASSIFICA

APPENDIX G

, 1

, , , t

·

## DEPARTMENT OF THE A JAY U.S. ARRYTHEE TRAVEL TO THE ARREST AND A 2001 FOR THE ARREST AND THE ARR

ATTACHED

DAPC-EPT-F

2 December 1983

SUBJECT: DA Funding for Aircraft Technical Inspector Training (66 Series MOS')


NQ, DA ATTN: DAMO-ZF (Mrs Ellard) The Pentagon Washington, DC 20310

- 1. The CMF 67 Revision requires training to Army Standards approximately 1500 soldiers during FY 84 and FY 85 to meet the initial Army requirements for qualified Aircraft Technical Inspectors (66 Series MOS'). CMF 67 authorization documents are currently undergoing revision to reflect the new MOS requirements. Personnel were selected for training to meet these new authorizations by a DA Selection Board.
- 2. The training program has been established to allow for completion of all required 66 Series MOS training to fill 100 percent of new authorizations by the end of FY 85. To successfully accomplish this training requirement, personnel must be scheduled TDY enroute or TDY and return.
- 3. At present, training seat allocations for early FY 84 are being filled by selected for training personnel in receipt of PCS instructions. Since 100 percent fill of training quotas cannot be maintained in this manner, massive 10Y and return requirements will be necessary.
- 4. Currently, MACONS are not funded to meet the TDY and return requirements. Minimum course length for the 66 Series MGS' is 11 weeks with a maximum of 20 weeks. Placing this financial burden on each MACOM to accomplish a DA directed training requirement is not appropriate. Therefore, request that funds be appropriated from the Open Allotrent for approximately 300 soldiers in FY 84 and 500 soldiers in FY 85 to attend the required 66 Series MOS training TDY and teturn.
- 5. Pequest this action receive expeditious processing so there will be no delay in neeting the Army training requirements.

MARK F. BRENMAN, JR LTC, GS Chief, Specialized Training Branch

APPENDIX F

# RECLASSIFICATION DATA



HEL SUP (AH-64/0H-58A) HEL SUP UH-1/UH-60 67640 FW SUP OBNS/UTIL SUP HVY/MED HEL SUP ATK 67740 67Y40 I 67R40 05019 67240 ACFT MAINT SENIOR SGT

68M30 ACFT WPNS SYS REP

68J40 SUP-ACFT FC REPAIRER 68K40 ACFT COMP REP SUP

## MOS DELETED


67W, 67240, 68M30

TECHNICALLY QUALIFIED E7 SUPERVISOR FOR A TWO IMPROVE SUPERVISION AND CAREER PROGRESSION. TECH INSPECTOR FOR EACH AIRCRAFT TYPE. RESTRUCTURE CMF 67 TO PROVIDE FOR: AIRCRAFT FAMILY,

REVISE AIT TO TRAIN A "DOER" AND NOT AN ASSISTANT REPAIRER.

REVISE TRAINING FOR SKILL LEVEL 30/40 SUPERVISORS. DEVELOP TRAINING FOR TECH INSPECTOR COURSES.

GRADE SUSTAINABILITY CMF 67 TOTAL FORCE



### **BACKGROUND**


- O REALIGNMENT NECESSARY BECAUSE OF:
  - TRAINING
  - JOB SATISFACTION
  - RETENTION RATES
  - PROMOTION OPPORTUNITIES ABOVE E5
- O REALIGNMENT WILL REQUIRE MAJOR RECLASSIFICATION EFFORTAPPROXIMATELY 2573 SOLDIERS
- O PROBLEMS FROMPTED STUDY IN 1979
- O VCSA APPROVED TRADOC PLAN IN 1981
- O IMPLEMENTATION DATE SET FOR 1 OCTOBER 1983

## <u>PURPOSE</u>

To REVIEW BACKGROUND AND PROVIDE UPDATE ON STATUS OF THE ARMY AVIATION MAINTENANCE CAREER MANAGEMENT FIELD 67 REVISION WHICH IS SCHEDULED FOR IMPLEMENTATION ON 1 OCTOBER 1983.

= 2

## ARMY AVIATION MAINTENANCE CAREER MANAGEMENT FIELD 87 REVISION



APPENDIX E

-----

100

.

.

.

### RECLASSIFICATION ACTIONS

SEP 82 - JAN 83

WORLDWIDE BRIEFING TOUR MILPERCEN/
 USATSCH TO UPDATE APPROXIMATELY 2200
 AVIATION SOLDIERS INTERVIEWED.

SURVEYS/QUESTIONAIRES, DISTRIBUTED DURING VISITS

NOV 82

- CMF 67 REALIGNMENT BRIEFED AT W/W MILPO CONFERENCE IN WASH D.C.

DEC 82

- RECLASSIFICATION AUTH CENTRALIZED
AT MILPERCEN LEVEL

MAR - MAY 83

- 2ND VISIT BY MILPERCEN/SSC/USATSCH TO LOCAL MILPO'S

JULY 83

- TEAM FROM MILPERCEN/USATSCH WILL MEET IN WASH D.C. TO ANALYZE ONSITE INTERVIEW DATA AND MATCH
AGAINST FORCE STRUCTURE REQUIREMENTS.

BASED UPON ABOVE DECISIONS ON RE-CLASSIFICATION WILL BE MADE. RECLASSIFICATION UPDATE

 $\hat{\nu}'_{\bullet}$ 

22 03

1:50th

YOUR COOKS IN CHEECTED FOR TOUTHER AND SCHOOLING IN A TRY AND RETERM CHARLES THE CHARLSAND ERRORS RELETED. CONTINUE STATUS.

L. UPON COMPLETION OF TRAININGS THE CUF BY CAREER ENAUCH BREE TAKE ACTION TO PRECEDE PCS MOVEMENT OF THESE SOLDIERS FOR LE MONTHE.

- 7. GOUEST MIDEST DISSEMINATION TO LOBEST LEVELS OF COUNAND.
- W. PUC AT RIEPERCEN IS MSG CORE/SPC MESMACH ABTOVOR E25-6522/6113.
- 9. MILPO PURKLOAD HAS BLED CONCIDENCO.

UNCLASSIFIED

35

APPENDIX H

#### RECLASSIFICATION ACTIONS

SEP 82 - JAN 83

- WORLDWIDE BRIEFING TOUR MILPERCEN/
USATSCH TO UPDATE APPROXIMATELY 2200
AVIATION SOLDIERS INTERVIEWED.

SURVEYS/QUESTIONAIRES, DISTRIBUTED DURING VISITS

NOV 82

- CMF 67 REALIGNMENT BRIEFED AT W/W MILPO CONFERENCE IN WASH D.C.

**DEC 82** 

- RECLASSIFICATION AUTH CENTRALIZED
AT MILPERCEN LEVEL

MAR - MAY 83

- 2ND VISIT BY MILPERCEN/SSC/USATSCH TO LOCAL MILPO'S

JULY 83

- TEAM FROM MILPERCEN/USATSCH WILL

MEET IN WASH D.C. TO ANALYZE ONSITE INTERVIEW DATA AND MATCH

AGAINST FORCE STRUCTURE REQUIREMENTS.

BASED UPON ABOVE DECISIONS ON RE-CLASSIFICATION WILL BE MADE.



## DEPARTMENT OF THE ARMY U.S. ARMY TRANSPORTATION SCHOOL FORT EUSTIS. VIRGINIA 23604

ATSP-CD-OR

11 July 1983

SUBJECT: Letter of Instruction (LOI) to CMF 67 Reclassification Board

Members of the Board

1. In accordance with the Department of the Army approved Career Management Field 67 (Enlisted Aviation Maintenance) revision, this Reclassification Board for selected CMF 67 soldiers is hereby called to order. The board will consist of the following voting members:

AVERY, CHARLES N. POLLOCK, DON L. *PINKHAM, MARTIN C. COLE, WALTER	MAJ	044-38-9425	President
	GS11	206-26-5649	Voting Member
	CPT(P)	322-38-5731	Voting Member
	MSG	238-72-3236	Voting Member
GARRISON, DOYLE M. HUMPHREYS, JACK NEWMAN, RANDY WORKS, GARY	MSG SFC(P) SFC SFC	464-60-0753 569-68-4217 429-02-2204 254-96-6156	Voting Member Voting Member Voting Member Voting Member

<sup>\*</sup>As required and available.

Non-voting members will be appointed by the president of the board to accomplish administrative work as required.

- 2. Authority to conduct this board is in accordance with the Chief of Staff Army Memorandum CS360, dated 5 May 1981, TRADOC tasker dated 6 July 1981 and the DCSPER approval of the CMF 67 revision on 20 December 1982.
- 3. The conduct of the board will be in accordance with the following general guidelines.
- a. The functional organization of the board will be 2 panels of 3 members each. They are Panel #1 Mr. Pollock, MSG Cole and SFC Humphreys. Panel #2 MSG Garrison, SFC Newman and SFC Works.
- b. Based on 3,000 records, each panel will attempt to review 200 records per day for a total board review of 400 records per day. This would complete the required 3,000 records in 7.5 days. Each panel will vote on their 200 records only. Voting will be done on the preprinted control numbered voting card.

ATSP-CD-OR SUBJECT: Letter of Instruction (LOI) to CMF 67 Reclassification Board

- c. Those soldiers who have a single qualification will be filed by appropriate MOS and grade. Multiple qualifications will be filed once MOS is selected in an order of merit listing based on scores.
- 4. Force Structure requirements are provided for each board member. These requirements will not be exceeded by more than 10% or less than 5%, i.e., 95 to 110% of force structure requirements.
- 5. The following four criteria will be the primary considerations of each panel member in coming to their decision:
- a. <u>Training and Background</u> Formal resident and nonresident training both military and civilian. Experience doing what he is trained to do.
- b. <u>Soldiers Desire</u> Desire must align with experience and/or training.
- c. <u>Commanders' Recommendation</u> Commander and 1SG or surrogate CO and 1SG if no recommendation or erroneous recommendations were made by CO and 1SG.
- d. Needs of the Army This will be considered during summation process. Force structure 95 to 110% are desired parameters.
- 6. The results of the vote (both single qualification and order of merit) will be tabulated. The results will be analyzed and force structure (Needs of the Army) parameters applied. Final listing will be released by board prior to the close of the board.
- 7. Any individuals whose records are not available for presentation at the board will be screened and reclassified at DA MILPERCEN by Aviation Enlisted Assignments branch personnel. These reclassifications will be accomplished in accordance with the criteria indicated in paragraph 5 above.
- 8. The board is scheduled to adjourn on 22 July 1983. A decision to extend the closing date of the board, if required, will be made by the President of the Board.
- 9. The overriding purpose of this board is to align the soldiers in CMF 67 with the new NOS contained in the CMF 67 revision effective October of this year. It is our job "to put the right man in the right job". It is not within the charter of this board or the CMF 67 revision to remove any soldier from the CMF 67 career field. Judgements regarding quality of

ATSP-CD-OR SUBJECT: Letter of Instruction (LOI) to CMF 67 Reclassification Board

service rendered or assignment potential will <u>not</u> be considerations of this board when considering a soldier for reclassification. The charter of this reclassification board will be to make an impartial and objective evaluation of each soldier within the guidelines stated in paragraph 5.

CHARLES N. AVERY

MAJ, TC

CMF 67 Reclassification Board President

#### DISTRIBUTION:

Mr. Pollock CPT Pinkham

MSG Cole

MSG Garrison

SFC Humphreys

SFC Newman

SFC Works



## DEPARTMENT OF THE ARMY U.S. ARMY MILITARY PERSONNEL CENTER 2461 EISENHOWER AVENUE ALEXANDRIA, VA 22331

ATTENTION OF

July 20, 1983

ATSP-CD-OR

SUBJECT: Closing Instructions to CMF 67 Reclassification Board

Members of the Board

- 1. In accordance with the Department of the Army approved Career Management Field 67 (Enlisted Aviation Maintenance) revisions, this Reclassification Board for selected CMF 67 soldiers is hereby adjourned.
- 2. The board considered 2650 soldiers for reclassification. Of those 2650 soldiers considered 2250 were reclassified to a new MOS. The 375 who were not reclassified were either not eligible or not most qualified. There exists a number of soldiers whose records were not available for consideration by the board. Their records have been ordered from Ft Benjmain Harrison. In accordance with paragraph 7 of the Letter of Instruction (LOI), DA MILPERCEN Aviation Enlisted Assignments Branch will consider these soldiers for reclassification.
- 3. The results of this board will be announced to the individual soldiers reclassified in the form of a personal letter to each soldier. This notification will be accomplished by DA MILPERCEN Aviation Enlisted Assignments Branch. Board members are sworn not to divulge any information concerning reclassification prior to the official notification by DA MILPERCEN. Board members may not divulge information concerning the procedures and/or methodology by the board at any time.
- 4. The boards charter was to "place the right man in the right job". This was accomplished. Each member of the board is to be congratulated for the professionalism with which you went about your task. Your concern for the careers of these soldiers will have a positive effect on not only the individual soldier but also Army Aviation.

MAJ, TC

CMF 67 Reclassification Board President

H5

ATSP-CD-OR

SUBJECT: Closing Instructions to CMF 67 Reclassification Board

#### DISTRIBUTION:

Mr. Pollock

CPT Pinkham

MSG Cole

MSG Garrison

SFC Humphreys

SFC Newman

SFC Works

SGT Suitt

SGT Orrick

SGT Baughman

CONTROL MUMBER

Theater Area Mumber

#### CHF 67 RECLASSIFICATION SURVEY

The purpose of this survey is to ascertain information about CHT 67 personnel who will require reclassification in accordance with the CHT 67 revision which will be eifective in October 1983. These surveys will become one of the wost important means that will be used to effect this reclassification. This survey will be a way for you to input your personnal desires and experience. Tou must treat this survey very seriously as it will effect your professional future. Honeat answers to each question will greatly enhance the design of this program to place the right man in the right job. All information contained within this survey will be handled in attrictest confidence and will be used solely for purposes of this reclassification.

#### PRIVACY ACT STATEMENT

Privacy Act Statement — 26 Sep 75: 1. Authority: Section 301 Title 5 USC.
2. Purpose: To obtain information on soldiers in OFF 67, pending reclassification.
3. Routine Uses: Same as Principal Purposes. 4. Handatory or voluntary information: Handatory disclosure of SSN necessary to properly identify the individual from others of the same last name.

4 7

4

The following questions must be answered to the best of your knowledge. If you need to refer to your personnel records for the information required, we recommend you do so. For the purposes of this survey, an HOS is defined as a five character identifier, i.e., 67H2O.

Complete all questions using a No. 2 pencil.

_	RAPIE:					
-		LAST	PIRST	MI	DDLE	
•	RANK:		·	•		
١.	SSN:		3A. O	STANDING PROHOT	ION LIST: YE	s NO
_	UNIT:	,		•		•
•		COMPANY	BH	DIV C	ORPS	
۸.	GEOGRA	PRICAL FOCALI	OH (AIRPIELD):			
١.	SRC NU	POER:		•		
۶.	MTOE P	OHBER:				
١.	MACOM:	:				
				BOW OBTAINED:	SCHOOL OJT OTHER (SPEC	WHEN OBTAINED_
<b>)</b> .	SECON	DARY HOS:	1	BOW OBTAINED:	SCHOOL OJT OTHER (SPEC	WREN OBTAINED
10.	. ADDIT	IOHAL MOS:	,	HOW OBTAINED:	SCHOOL OJT OTHER (SPEC	WHEN OBTAINED .
11.	. PRESE	אד DUTT HOS:	· .			
12	. PRESE	NT DUTT POSIT	ION:			
13			UTT POSITIONS HE ST RECENT IN CAL	LLD SINCE ENTERIM ENDAR YEARS.	G THE ARMY IN	ORDER FROM
	MOS	DUTY POS	ITTON	PROM	<u>10</u>	YEAKS
A.	,					
В.						
c.			i		•	

	·
D.	•
E.	
¥. /	
C.	,
H.	
ı.	
J.	
14.	DISRECARDING TOUR PAST EXTERIENCE, WHAT AVIATION HOS CONTAINED IN THE CHY 67 REVISION WOULD YOU DESIFF TO HOLD IF YOU HAD THE OPPORTUNITY?
	with contractive of
15.	HAVE YOU EVER BELL AT AVIATION TECHNICAL INSPECTOR? YES NO
	IF YOU ANSWERED YES TO QUESTION 15, ANSWER QUESTIONS 16 THRU 20. IF TOUR ANSWER WAS NO, CO TO QUESTION 21.
	NOTE: ADDITIONAL SPACES ARE PROVIDED FOR MULTIPLE ENTRIES.
16.	WHAT HOS DID YOU HOLD WHEN YOU WERE A TECHNICAL INSPECTOR?
17.	NOW DID YOU OBTAIN THIS MOS? SCHOOL OJT OTHER
13.	WIEN DID TOU OFTAIN THIS EUS?
19.	WHAT TYPE AIRCRAFT WERE TOU A TECHNICAL INSPECTOR FOR? 1.E., UH-1H, OV-1A, ETC.
20.	WHEN WERE YOU A TECHNICAL INSPECTOR? FROM: TO:
21.	BASED ON YOUR PAST EXPERIENCE, MINT AVIATION HOS CONTAINED IN THE CHE 67 REVISION WOULD YOU DESIRE TO THE CHE 67 MIN / / / / / / / / / / / / / / / / / / /
22.	BASED ON YOUR PAST PRIMERAGES. MINT AVIATION HOS CONTAINED IN THE CAP 67 REVISION DO YOU FEEL YOU, HE MOST QUALIFIED FOR?
	WHY (PRIES STATEM) "

17 9

WHEN YOU COMPLETE QUESTION 22, REVIEW YOUR ANSWER TO ALL QUESTIONS. WHEN YOU ARE SATISFED THAT ALL ANSWERS ARE ACCURATE! PLEASE RETURN THE FINISHED SURVEY TO YOUR 15G. THANK YOU FOR YOUR COOPERATION.

QUESTIONS 23 THRU 27 SHOULD BE ANSWERED BY BOTH THE ISC OR DIS EQUIVALENT AND THE COMMANDER. YOU ARE MOST EMONIECCEABLE ABOUT YOUR FEOPLE AND YOUR ANSWERS WILL GREATLY EMMANCE THE EFFECTIVENESS OF THIS RECLASSIFICATION. ALL ANSWERS WILL BE TREATED WITH STRICTEST CONFIDENTIALITY. FLEASE REGENERA TO CHECK THE ANSWERS TO QUESTIONS 5 THRU 7.

- 23. HOW LONG HAS THIS SOLDIER BEEN ASSIGNED TO YOUR UNIT?
- 24. IS THIS BOLDIER WORKING IN HIS PRIMARY HOST YES NO NO
- 25. IF THE ANSWER TO QUESTION 24 IS NO. IN WHAT HOS IS THE SOLDIER MORNING! HOS!
- 26. IN MIAT HOS CONTAINED IN THE CHE 67 REVISION DO THE EVEL THIS SHIDLER MOULD BEST SERVE THE ARMY? ISO COMMANDED

IF THE ANSWER TO MIMBER 27 IS YES, PLEASE TAKE A BLANK SHRVET FOR EACH AND HAVE THEN FILL IT OUT MIEN THEY ARE AVAILABLE. MAIL CONTLETED SHRVETS AS SOON AS POSSIBLE TO: DA, HILFERCEN, ATTN: DAFG-EPL-T, 2461 EISENHOUER AVE. ALEXANDRIA, VA 22331.

. . . . .

,

## MOS AND GRADE REQUIREMENTS AFTER CMF 67 REALIGNMENT


MOS	PAYGRADE	HTUA	*NUMBER OF SOLDIERS IDENTIFIED FOR THIS GRADE/MOS
66C	5 6	6 55	<b>5</b> <b>4</b> 0
<b>6</b> 6H	5 6	9 15	10 14
66V	5 6	127 138	62 137
66N	5 6	- 176 257	116 225
66Y	5 6	82 103	53 106
66T	5 6	63 88	5 86
<b>6</b> 6U	5 6	46 69	8 66
66J	6	113	53
68J	7	116	109
67G	7	84	122
67T	7	455	621
<b>6</b> 7Y	7	420	513
<b>6</b> 7U	7	150	235
	TOTA	LS 2572	2586

--'

ŧ

~--

# RECLASSIFICATION DATA



HEL SUP (AH-64/0H-58A) 67140 HEL SUP UH-1/UH-60 67640 FW SUP OBNS/UTIL HEL SUP HVY/MED HEL SUP ATK 67040 67R40 0<del>1</del>440 67240 ACFT MAINT SENIOR SGT

68J40 SUP-ACFT FC REPAIRER 68K40 ACFT COMP REP SUP

## MOS DELETED

67W, 67Z40, 68M30

- 3. Option 3. To Ensure That All Commands, Including FORSCOM, Document All Administrative Changes (That is, All Changes Which Do Not Require Resourcing) in Their Current Documents.
- a. This is in fact what has been occurring in FORSCOM and the other NACOMs. This would be a continuation of current practices and would be in accordance with AR 310-49, not affect readiness as stated in AR 220-1 and still provide the Army the advantages foreseen by the restructure effort.
- b. Under this option, other changes would be documented when resources become available either from trade-offs in existing authorizations or from additional manpower allocations.

#### SECTION II - CONCLUSIONS

Options: The Army has three options, as I see them. These together with the perceived impact/practicability of each are:

- 1. Option 1. To Allow FORSCOM To Not Document Any of the Changes For CMF 67 As Shown in CCT 300-74.
- a. This approach would please the FORSCOM community, but would separate them from the rest of the Army. Assuming that documentation of the other MACOMs proceeds as agreed, would mean that their aviation maintenance structure would be different from the remainder of the Army. Some of their personnel would carry obsolete MOS and action dependent on programs contained in automated systems may no longer occur because of edits in those systems.
- b. The morale and management of FORSCOM personnel would be adversely impacted. Selection for training, assignment and promotion would be based on the revised system.
- 2. Option 2. To Delay Implementation of the CMF 67 Structure Until the Plus-ups Can Be Provided.
- a. This approach would please the FORSCOM community, and the entire Army structure would remain as is.
- b. The adverse impacts would appear to be in two areas: personnel management and aircraft maintenance.
- (1) Much has been done to tell our aviation soldiers the advantages of restructure to them. Hundreds of individual soldiers have been interviewed and reclassification decisions have been made. Briefing teams have praised the system, publications have lauded the improvements in personnel management. To cancel or delay implementation would be an action difficult to sell to the 17,000+ soldiers affected.
- (2) There have historically been problems in swiation maintenance. The new structure was established to address these problems and to improve maintenance, and the safety of military aircraft. FORSCOM personnel state that the restructure is a sound one. To not restructure would be to retain the unsatisfactory aspects of the current structure.
- (3) Service schools training is in place to accommodate the revised structure.
- (4) Many areas of documentation have already been accomplished; automated systems are being, or have been, changed to manage the revised structure.

Jul 2

- 2. <u>Problem</u>: The FORSCOM Documentation Division interprets the substantive change definition as stated above, and it appears that all changes, other than for CMF 67, contained in CCT 300-74 to implement Change 20, AR 611-201, are currently being documented as administrative changes without difficulty. The Commander, FORSCOM, is apparently personally opposed to the partial documentation of CMF 67, (i.e., an all or nothing application of the CMF 67 restructure) because of the plus-up requirement at full implementation. He has confirmed his opposition through one, or more, back channel messages to General Thurman.
- a. FORSCOM has (at least since CCT 300-60) not documented nonresourced changes contained in CCT in current documents. In the case of aviation units, the 82nd Airborne Division's Aviation Units are fully documented through CCT 300-70; all other FORSCOM Aviation Units are documented through an earlier CCT, dependent on the extent that resources have been provided. Since several CCT have not been wholly documented prior to CCT 300-74, to fully implement all current and previously unresourced CCT changes for FORSCOM Aviation Units will require 800+ additional personnel. To enter these numbers of spaces in the required column of FORSCOM Aviation Unit MTOE's would adversely impact on FORSCOM readiness reports.
- b. For CCT 300-74, FORSCOM has taken the stand that they should not document either substantive or administrative changes as they pertain to CMF 67. General Thurman's guidance, when he approved the CMF 67 restructure was to implement administrative changes but not to authorize any CMF 67 increases without internal trade-offs. FORSCOM does not have available to them sufficient spaces to document substantive changes, and because of this, they oppose any changes to their documents for CMF 67.
- 3. USAREUR Approach: I have called and discussed documentation of Change 20, AR 611-201, changes with MSG Sudberry, USAREUR DCSREM. I am informed that USAREUR has nearly completed all Change 20 documentation, including CMF 67 changes. There are a few CMF 67 spaces which have not yet been converted, but the DCSREM is awaiting input from their units. MSG Sudberry assured me, however, that all changes would be made before close of the current MOC Window. USAREUR documentation efforts do not include documentation of unresourced requirements.

12 5

#### SECTION I - FINDINGS

#### 1. Background:

- a. Message, DAMO-FDP, HQDA, 251449Z Apr 83, stated in part:
- "1. Substantive changes contained in CCT 300-74 will not be documented until HQDA can assess the personnel and equipment impact of this CCT. Administrative changes may be documented. Once an impact analysis of CCT 300-74 has been completed, this office will publish guidance on documenting 300-74."
- b. Administrative changes are defined in paragraph 2-2d, AR 310-49, as those which, "do not require a new document. These type of changes may be applied by an administrative Consolidated Change Document (CCD) to existing approved documents. Examples of such changes are:
- (1) Line Item Number (LIN), Position Occupational Specialty Code (POSC), Army Management Structure Code (AMSCO), Additional Skill Identifier (ASI), and Language Identifier (LIC) conversions that are results of revisions in the governing HQDA regulations.
  - (2) Unit, paragraph, or job title changes.
  - (3) Correction of document errors.
- (4) Other changes that may increase clarity or definition and do not place requirements on HQDA for manpower, equipment or funds."
- c. Substantive changes, as defined in paragraph 2-2e, AR 310-49, "require a new document when there is a change as follows:
  - (1) Mission and organization (Section 1 of the document).
- (2) Total unit requirements or authorizations (Section II of the document).
- (3) Total unit requirements or authorizations by generic identifications (Commissioned Officers, Warrant Officers, Editson, Civilian).
  - (4) ...
  - (5) ..."
- d. We are used, it appears, to using "documentation" to assume that all\_CCT and other changes are entered into documents. To the contrary, paragraph 2-21h, AR 310-49, provides that nonresourced changes will be presented to HQDA (DAMO-FDP) for resourcing before documentation. As illustrated above, documentation can include either, or both, substantive and administrative changes.

K"U

Jul 1



#### DEPARTMENT OF THE ARMY US ARMY SOLDIER SUPPORT CENTER NATIONAL CAPITAL REGION 200 STOVALL STREET ALEXANDRIA, VIRGINIA 22332

27 JUL 1983

MEMORANDUM FOR DIRECTOR OF MILITARY OCCUPATIONAL DEVELOPMENT

SUBJECT: Documentation of CMF 67 (Enlisted Aviation Maintenance) Changes, Change 20, AR 611-201

- 1. On 22 July 1983, I visited Headquarters, US Army Forces Command (FORSCOM), Fort McPherson, Georgia. My purpose for going to FORSCOM was to determine that command's position on documenting the changes we had made to Change 20, AR 611-201.
- 2. I met with the following persons during the morning of 22 July:
  - a. LTC Joe Flesch, Chief, STRAF Branch, Documents Division, DCS Operations;
- b. CW4 Percy D. Butler, Personnel Staff Officer, Personnel Readiness and Distribution Division, DCS Personnel;
  - c. SGM Pandy, STRAF Branch, Documents Division, DCS Operations;
- d. Other interested personnel representing the DCSLOG and DCSOPS Aviation Division; and,

in the afternoon. I met separately with the following personnel:

- e. MAJ D. S. Lesher, Chief, Enlisted Personnel Division, Adjutant General;
- f. Mr. Lynn Chambers, Personnel Management Specialist, Enlisted Personnel Management Division;
  - command Sergeant Major Backer, Office of the Commanding Seneral.
- 3. My findings are included in Section I, attached hereto. My conclusions are in Section II and my recommendations are slated in Section III.

4 Incl

Section I - Findings

Section II - Conclusions
 Section III - Recommendations
 References

DONALD F. LANE

Military Occupational Management Specialist

U	N	C	L	A	3
---	---	---	---	---	---

PAGE 2
CONTAINED WITHIN THE AR 611-201 PROPOSAL. THIS IS SCHEDULED TO BE
ACCOMPLISHED BY THE MACOMS IN THE JUL-SEP 83 MOC WINDOW SUBSEQUENT
TO THEIR RECEIPT OF THE CCT IN APR 83 IAW MILESTONES APPROVED AT THE
JUNE AVIATION FUNCTIONAL REVIEW. AS A RESULT OF THE DCSOPS NONCON+
CURRENCE, IT IS MY UNDERSTANDING DCSPER PROJECT OFFICERS HAVE NONCONCURRED WITH THE AR 611-201 PROPOSAL.

3. IT WOULD BE EXTREMELY COUNTER PRODUCTIVE TO THE ARMY IN TERMS OF
INCREASED OPERATIONAL READINESS AND AVIATION SAFETY TO POSTPONE OR
ELIMINATE THE IMPLEMENTATION OF THIS ESSENTIAL PROGRAM. I SOLICIT
YOUR SUPPORT IN RESOLVING THIS RESOURCING SITUATION AND IN RESTORING
THE IMPLEMENTATION TO THE REALISTIC MILESTONES WHICH PRESENTLY EXIST.

SSD NOTE: DELIVER DURING NORMAL DUTY HOURS.
#4631

MNNN

UNCLAS

 $K^{-2}$ 

UNCLAS

ZCZCRPQ924
DAN: 026-032212
INPUT CDSN = KOA097
TOR: 171446Z DEC 82 TDT: 171446Z DEC 82

PAGE 1

OTTMZYUW YEDAGS 4631 3511442-MNSH--YEKDQO.
ZNY MMNSH
ZKZK OO SOA DE
O 171300Z DEC 82 ZYH
FM SSD TRADOC
TO SSO DA
INFO SSO RUCKER
ZEM
UNCLAS EYES ONLY
QQQQ
EYES ONLY//EYES ONLY//EYES ONLY//EYES ONLY//EYES ONLY//

SSO DA FOR LTG THURMAN, DA DCSPER SSO DA INFO MR. CRIBBINS, ODCSLOG-ZD SSO DA INFO MG ARTER, CDR, MILPERCEN SSO RUCKER INFO MG MCNAIR, CDR, USAAVNC FROM MG SMALL, COMDT, USATSCH

SUBJ CMF 67 RESTRUCTURE PROPOSED CHANGE TO AR 611+201, CHANGE 20 1. I AM VERY CONCERNED WITH THE VERY RECENT DCSOPS AND DCSPER PROJECT DFFICER NONCONCURRENCE WITH THE CMF 67 RESTRUCTURE. IT IS MY UNDERSTANDING THAT THIS NONCONCURRENCE IS NOT BASED ON FAULTS CONTAINED WITHIN THIS HIDELY ACCEPTED AND MUCH NEEDED REVISION BUT RATHER ON AN INABILITY TO RESOURCE THE REQUIRED MANPOWER PLUS UPS CONTAINED WITHIN THE PROGRAM.


2. THE PROPOSED CHANGE TO AR 611-201 WAS HANDCARRIED TO SOLDIERS SUPPORT CENTER ON 3 JUN 82. THE PROPOSAL INCLUDES A SCRUB OF BASE TOE ORGANIZATIONS TO A SRC LEVEL OF DETAIL AND TDA ORGANIZATIONS TO A UIC LEVEL OF DETAIL IN ACCORDANCE WITH THE REVISED STANDARDS OF GRADE. SUBSEQUENT TO YOUR AVIATION FUNCTIONAL REVIEW ON 16 JUN 82, HE PROVIDED YOUR STAFF WITH AN EXTRACT FROM THE PROPOSAL LISTING THE MANPOWER PLUS UPS BY GRADE AND MOS BY MACOM. DCSOPS HAS INDICATED THAT IN ORDER TO RESOURCE THE REVISION IN THE POIP AND POM PROCESS THEY REQUIRE A UIC LEVEL OF DETAIL (MTOE) REGARDING MANPOWER REQUIREMENTS. THIS UIC LEVEL OF DETAIL WILL NOT BE AVAILABLE UNTIL THE INFORMATIONAL MACOMS SCRUB THEIR RESPECTIVE MTOE IAW THE BASE TOE AND SGA

UNCLAS

K

APPENDIX K

## CMF 67 RECLASSIFICATION THE GO/NO GO DECISION




- · 1 FEB 84 IS THE MILPERCEN DROP DEAD DATE
- IF DOCUMENTATION IS NOT CORRECT, CMF 67 RECLASSIFICATION WILL BE DELAYED.

J

\_\_ 4

## CMF 67 DOCUMENTATION

## CURRENT STATUS:



### IMMEDIATE ACTIONS

- L DISAPPROVE INCORRECT DOCUMENTATION ARSTAF
- 2 REINSTATE CLD DOCUMENTATION IN AIRCMATED \_\_ ARSTAF SYSTEMS.
- 3. COMPLETE DOCLIMENTATION CORRECTIVE

  ACTION BY 30 NOVEMBER


  (ARSIAF SUPPORTED)

- 6. RECLASSIFICATION DECISION NIT I FEB --- MILPERCEN

### CMF 67 DOCUMENTATION PROBLEMS & PROPOSED SOLUTIONS

- . ALMOST ALL DOCUMENTS CONTAIN SIGNIFICANT PROBLEMS WITH DOCUMENTATION
- ERROR RATE FOR TYPICAL DOCUMENT EXCEEDS 75%
- . PROBLEM AREAS:
  - .. STANDARDS OF GRADE HOT APPLIED
  - .. 66 SERIES MOS ITECH INSPINOT DOCUMENTED OR DOCUMENTED INCORRECTLY
  - .. TECH INSPECTORS BEING DOCUMENTED OUTSIDE 66 SERIES MDS
  - .. 40 LEVEL CAPPER MOS NOT DOCUMENTED OR DOCUMENTED INCORRECTLY
  - .. SOME INCORRECT MOS CHOSEN
  - .. NUMBERS OF AUTHORIZATIONS INCORRECT

#### **EXAMPLES OF DOCUMENTATION ERRORS**



#### PLAN FOR CORRECTION

USAAYNC/USAALC AND SSC-NCR TAKE LEAD TO RESOLVE PROBLEMS

- .. ESTABLISH 7-DAY REDOCUMENTATION PERIOD AT SSC-NCR
- .. MACOMS PROVIDE DOCUMENTORS
- .. NODA DIRECT CHANGES DURING SPECIAL NOV 83 MINI-MOC WINDOW

J

APPENDIX J

GRADE SUSTAINABILITY CMF 67 TOTAL FORCE



Apardio I

I

APPENDIX I

#### SECTION III - RECOMMENDATIONS

- 1. That FORSCOM be instructed to document all administrative (nonsubstantive) changes to implement CMF 67 changes IAW the DCSPER's approved instructions.
- 2. That FORSCOM units reclassify their CMF 67 soldiers using current guidance.

Inci 3

28

#### MILITARY PUBLICATIONS

## THE ARMY AUTHORIZATION DOCUMENTS SYSTEM (TAADS) RCS CSGPO-375

Effective 15 January 1981

2-21. Organization of MTOE units. a. Policies and criteria in AR 310-31 for developing TOEs generally apply to developing MTOEs. Added guidance and criteria to assist in developing MTOE units are also contained in other DA publications such as AR 310-34 and AR 570-2.

b. TOEs are not authorization documents. They serve only as a base from which to develop MTOE. The published TOE provides a dission-oriented organization with the personnel and equipment requirements for combat, combat support, and

combat service support type units.

c. A unit will be organized under the proper level of its TOE, including the latest published change, to the greatest extent consistent with the unit's mission and the availability of manpower spaces and equipment resources. Noncellular TOE will be used to the greatest extent practicable; cellular TOE will be used only when a noncellular TOE does not exist for the predominant mission or organizational structure.

d. Like-type units organized under a TOE will be standardized and documented on a single MTOE when possible. Command, mission, and location may dictate separate MTOEs for like-type units in different commands. Exceptions to standardization of like-type units requires approval by HQDA. Requests for exceptions must be fully justified to include line and LIN detail.

e. Units will be assigned the highest ALO possible within the constraints of military spaces

available.

f. The organizational structures of MTOE units required to submit unit status reports according to AR 220-1 will be combat oriented. Personnel positions, items of equipment, and accompanying supply allowances will be limited to those required for sustained combat operations and support of such operations. Provisions will be included in higher echelon units to offset any intermittent

...

requirements of the lower echelon units on a customer or support basis.

g. Combat support and combat service support unit authorizations should be based upon the

authorizations for the units supported.

- A. The required column of an MTOE will be developed from the Level 1 or Type B column of the TOE, as applicable. (See para 2-22, below for development of Type B MTOEs.) HQDA (DAMO-FDP) must approve any modification or deviation from the documentation of TOE Level 1 or Type B allowances in MTOE required columns. The authorized column of an MTOE will be developed based on the unit ALO along with manpower and equipment resources availability. TOE CCTs will be applied to MTOEs according to the following guidance:
- (1) MTOE required columns will be changed to reflect the Level 1 or Type B column of the latest CCT.
- (2) CCTs that do not place increased resource demands on HQDA will be documented in MTOE authorized columns at the applicable ALO. CCTs that place increased resource demands on HQDA will not be documented in MTOE authorized columns without prior approval by HQDA. Proponents will identify such increased resource demands and submit requests for resourcing to HQDA(DAMO-FDP).
- (3) Documenting semiannual CCT changes not requiring HQDA approval will be completed during the management of change (MOC) processing cycle following publication of the CCT. For example, April CCT changes will be documented during the July to September MOC cycle of the same year.

#### APPENDIX A

#### EXPLANATION OF TERMS

Va. Administrative change. A nonsubstantive change to an authorization document. This type of change does not require creation of a new document. (See para 2-2d for a description of the changes categorized as administrative.)

✓ ap. Substantive change. A change to an authorization document which, because of its substantive nature, requires a new document. See paragraph 2-2c for a description of the type changes that are categorized as substantive.

Irel 4

六

ARMY REGULATION No. 220-1

HEADQUARTERS
DEPARTMENT OF THE ARMY
WASHINGTON, DC 1 June 1981

#### FIELD ORGANIZATIONS

## UNIT STATUS REPORTING Requirement Control Symbol JCS 6-11-2-1-6

Effective 16 July 1981

- 3-6. Personnel Readiness data. Review the explanations of assigned strength full required MTOE strength (Glossary), and available strength (app B), compute and enter data in blocks 15 through 25 as follows:
- a. Blocks 15, 16, 17 (assigned strength percentage). Divide the assigned strength by the required MTOE strength and convert to a percentage. Enter the percentage.

EXAMPLE:

- (1) Assigned strength will equal the accountable atrength of the latest PCN: AAC-CO5, Unit Strength RECAP Part II, adjusted to the "as of" date of the status report. This is done by adding gains and subtracting losses which have occurred since the date of the unit strength RECAP Part II. For Reserve Component units, assigned strength includes the full-time manning personnel assigned on a separate TDA that would deploy with the unit if mobilized as of the date of the report.
- (2) Include Office of The Surgeon General (OTSG) officer fillers and earmarked Army Medical Department (AMEDD) officers in the available strength as follows:
- (a) For FORSCOM and WESTCOM active component nedical units. The Surgeon General (TSG) will provide AMEDD officers (OTSG fillers) when a FORSCOM or WESTCOM unit is selected for a mission that requires full MTOE staffing. Compute rating of a FORSCOM or WESTCOM unit on the basis that all AMEDD officer required assets are available.
- (b) For all other medical units. Compute the personnel rating on the basis that assigned personnel (plus those AMEDD officer fillers who are earmarked for assignment to the reporting units on alert, deployment, or initiation of a combat mission) are available. Do not consider critical unit medical

personnel on the Post Mobilization (M.Day) Deployment List (PMDL) as available for reporting the status of USAREUR or EUSA medical units. Oversea commanders who provide earmarked AMEDD

personnel will send feeder information, including POR and MOS qualification of designees, to the reporting commanders no later than 15 days before the end of the report period. This will permit reporting unit commanders to include necessary information in status reports. Personnel or equipment will not be earmarked to more than one reporting unit. Personnel assigned to a reporting medical unit, who under alert, deployment, or combat conditions are earmarked to another unit, will be reported by the unit to which earmarked.

- (c) Authorization not reduced. Applying the provisions of this paragraph does not reduce medical unit personnel authorizations.
- b. Blocks 18 and 19 (available strength percentage). All units will report available strength percentage.
- (1) Determine the number of personnel who are available under the criteria in appendix B. Divide the available strength by the required MTOE strength, convert to a percentage. Enter the percentage.

EXAMPLE:

- (2) Each unit will report required, authorized, assigned, and available strengths on PSPER remarks cerd. (See para 2-32d(1) and fig. 3-2.) Additionally, PSPER remarks will include the total number of females assigned to the unit and the number pregnant. If available strength is more than 5 percent (10 percent company size and smaller units) lower than assigned strength, in PSPER remarks state the main factors that contribute to the condition. (It is not necessary to explain a greater—than 5 percent difference if caused by space limitation of blocks 18 and 19, e.g., assigned strength 109 percent and available strength 104 percent.)
- c. Blocks 20 and 21 (available MOS trained percentage). Divide the available MOS trained strength by the required MTOE strength and convert to a percentage. Enter the percentage.
- (1) Determine the number of MTOE personnel spaces required by identity (officer, WO and en-

Jucy,

1210

listed) and by Military Occupational Specialty Code (MOSC).

- (2) Determine the number of personnel included in the available strength of the unit by identity and MOSC. Match the trained available personnel against the spaces in the MTOE required column. Determine which personnel are to be considered as trained for purposes of this report as follows:
- (a) Match officers to officer spaces on a onefor-one basis. Officers may be considered MOS qualified insofar as skill level is concerned when the commander feels that they have minimum skills needed to perform the wartime duties of the position. They must also hold grades within two grades higher or lower than that required by MTOE.
- (b) Using only the first three characters of the MOSC, consider WO and enlisted personnel MOS trained when they call be used in their primary MOSC (PMOSC), secondary MOSC (SMOSC), additional MOSC (AMOSC), or a substitutable MOSC for the above. Exception: Where a special qualification is mandatory and shown in the fifth character, e.g., 11B2P, five characters must be considered. See AR 611-201.
- (c) Reserve Component units, REP 63 trainees, and other personnel in MOS producing training should not be considered MOS trained until they are awarded MOS and returned to the unit. This also includes ROTC cadets and OCS candidates.
- (d) Do not consider those MOS trained personnel who are overstrength in a specific skill, AWOL, or in confinement and who are not used as described above. For example, if a unit is authorized four cooks and has six MOS qualified cooks in its assigned after the nount only four egainst the outhorization for cooks. However, if the two surplus cooks have SMOSC or AMOSC of truck drivers and are qualified to drive trucks, and if vacancies exist for truck drivers, then count those cooks as MOS trained drivers.

EXAMPLE:

Available MOS trained atrength x 100
Required MTOE atrength

 $=\frac{561}{}$  × 100 = 72.3

20 21 7 2

d. Blocks 22 and 23 (available senior grade percentage). Add the number of available officers, WO, and grades E5 through E9. Divide the result by the

to all number of officers, WO, and grades E5 through E9 required by full MTOE. Convert to a pyrcentage. Enter the percentage.

- e. Blocks 24 and 25 (personnel turnover percentage). Divide the number of personnel reassigned or discharged from the reporting unit during the preceding 3 months by the operating strength (on the report "as of date"). Convert to a percentage. Enter the percentage.
- (1) Do not count transfers within the reporting unit.
- (2) Reserve Component reporting units will base computations on the preceding 6 months.

  3-7. Equipment-on-hand data.

a. Blocks 2F \*\*

Juck 4,

X

11

\* UNCLASSIFIED \*

TOR = 831151542 283115/10552RITUZYUK RUEADND2814 1151629-UUUU--RUEAHOF. ZNR UUUUU R 251449Z APR 83 FM HR DA WASHDO//DAMD-FDP// TO RUFDAAA/CINCUSAPEUR AND SEVENTH ARMY HEIDELBERG GE //AEAGF// RUAGAAA/CDR EIGHTH US ARMY SEDUL KOREA //CJ-FD// RUCLAIA/CDR TRADOC FT MONROE VA //ATCD-0// PUCLAIA/CFR FORSCOM FT MCPHERSON GA //AFOP-FDC/AFOP-FSA// RUKLDAR/CDRDARCOM ALEX VA //DRXMM-T// RUHHHMA/CDPWESTCOM FT SHAFTER HI //ADCP-FD// RUNJHRA/CDPUSACC FT PUACHUCA AZ //CC-FD// RUDHAAA/CDRINSCOM AHS VA //IARM// RUEAHOF/CDR MILPERCEN ALEX VA 1//DAPC-CS// RUEAHOF/DEP COR SSC-NCR ALEX VA //ATZI-NCR-DC// PUEAUSA/CH ARNE WASH DC //MGB-ZA//. PUEADWO/CH APC W/SH DC //DAAP-DTZ// RUEADWD/HQ DA WASHDC//DAMO-DD/DAMO-RQ/DAPE-HB/DALG-PLF/ DAMD-FM// BT.. \_\_\_\_

DIX-CS Pil

SUPJECT: DOCUMENTATION OF CCT 300-74

1. SUBSTANTIVE CHANGES CONTAINED IN CCT 300-74 MILL NOT BE
DOCUMENTED UNTIL HODA CAN ASSESS THE PERSONNEL AND ERUIPMENT IMPACT
OF THIS CCT. ADMINISTRATIVE CHANGES MAY BE DOCUMENTED. ONCE AN
IMPACT\_AMALYSIS OF CCT 300-74 AND RESOURCING PROCEDURES HAVE BEEN
COMPLETED, THIS OFFICE WILL PUBLISH GUIDANCE ON DOCUMENTING CCT 30074. ADDITIONAL INFORMATION WILL BE PROVIDED DURING THE 3-5 MAY 83
MIDE STANDARDIZATION CONFERENCE AT HODA.
2. POC THIS OFFICE IS LTC GWYNN VAUGHAN, AV 225-6575.

3T
72814

ية بير

PAGE 01 251449Z APR 83 RUEADWD/2814 K12

girc 4,

CDRUSAAVNC FT RUCKER AL //ATZQ-CG

CDRUSAFORSCOM FT MCPHERSON GA

CINCUSAREUR HEIDELBERG GER

CDRUSAEIGHT SEOUL KOREA

CDRUSATRADOC FT MONROE VA //ATCD/ATTG//

CDRUSADARCOM ALEX VA

CDRUSAMESTCON FT SHAFTER HI

CDRUSARJ CP ZAMA JAPAN

CDRUSACC FT HUACHUCA AZ

CDRUSACE WASH DC

CDRHTHC WASH DC

CDRMDU WASH DC

CDRUSAINSCON AHS VA

CDRUSAHSC FT SAM HOUSTON TX

CDRUSACIDE WASH DC

CDRUSASSO FT BENJAMIN HARRISON IN //ATZI-CG//

IMPO HODA WASH DC //DACS-ZB//

Od HZAU ERMO

HODA UASH DC //DACS-ZD/DACA/DAMA/DALO/DAMO-FDX/

F.D.BETTINGER, COL, GS, DEPCDRUSASSCH NCR, ATZI-NC/23D-835U/24 OCT 35

SOBBY J. MADDOX-MG-USA/CDRUSAAVNC/ EUG-EEG-EG-DSTA

UNCLASSIFIED

K 13

DAMO-FDY/DAMO-TR/DAPE-MP/DAPE-MB/DASG/DAMI/

DAIG/DAEN/DACS-DM/DACS-DP/DAAR/DAAG//

CDRUSAREC FT SHERIDAN IL

CDRUSAMILPERCEN ALEX VA //DAPC-EP/DAPC-PL//

CDRUSAALC FT EUSTIS VA

UNCLAS

XODEAN OR GOZ

SUBJ: CMF 67 RESTRUCTURE

- A. CHANGE 20. AR bin-201.
- B. LON-E-20-7, 13 JAN 83.
- C. DOC MOD HIS NUMBER I EDOCHOD IJ.
- THE AVIATION LOGISTICS CENTER AND THE USASSC-NCR HAVE REVIEWED MACON DOCUMENTATION IMPLEMENTING THE CMF L7 RESTRUCTURE. RESULTS OF THE REVIEW INDICATE SIGNIFICANT ERRORS/ONISSIONS IN APPLICATION OF THE CMF L7 RESTRUCTURE GUIDANCE SPECIFIED IN CHANGE 20. AR L12-201 (REF A). IN VIEW OF THE SIGNIFICANT DOCUMENTATION DEFICIENCIES. RECLASSIFICATION OF PERSONNEL PLANNED FOR 1 APR 84 CANNOT OCCUR UNTIL THE CMF L7 RESTRUCTURE IS DOCUMENTED CORRECTLY.
- 2. ERRORS NOTED DURING THE REVIEW INCLUDE:

UNCLASSIFIED

KIU

- A. REVISED SGA NOT APPLIED CORRECTLY.
- B. TECHNICAL INSPECTORS (MOS bb SERIES) NOT DOCUMENTED OR DOCUMENTED INCORRECTLY.
- C. TECHNICAL INSPECTOR POSITIONS DOCUMENTED OUTSIDE OF 66 SERIES MOS.
- D. SKILL LEVEL 40 CAPPER MOS NOT DOCUMENTED OR NOT PROPERLY DOCUMENTED.
  - E. INCORRECT MOS APPLIED TO SELECTED POSITIONS.
  - F. QUANTITY AUTHORIZED INCORRECT.
- J. IN ORDER TO EXPEDITIOUSLY CORRECT THE DOCUMENTATION

  DEFICIENCIES, THE USAAVNC/AVIATION LOGISTICS CENTER IN CONJUNCTION

  UITH USASSC-NCR WILL HOST A CONFERENCE TO "FIX" THE DOCUMENTATION.

  HACOMS ARE REQUESTED TO SEND QUALIFIED REPRESENTATIVE(S) TO

  PARTICIPATE IN THE SCRUB AND CORRECT DOCUMENTATION ERRORS. THE

  CONFERENCE WILL BE HELD IN THE HOFFMAN BUILDING II (ROOM BN33)

  IN ALEXANDRIA, VA, COMMENCING AT D300 HOURS, 14 NOV 83.

  4. SINCE DOCUMENTS MUST BE CORRECT BEFORE PERSONNEL CAN BE
- 4. SINCE DOCUMENTS MUST BE CORRECT BEFORE PERSONNEL CAN BE RECLASSIFIED WITHIN THE NEW STRUCTURE, YOUR PARTICIPATION IS CONSIDERED ESSENTIAL. FAILURE TO CORRECT THE DOCUMENTS WILL,

UNCLASSIFIED

1515

IN TURN, IMPACT ADVERSELY ON THE CAREERS OF SOLDIERS. PERSONNEL MANAGEMENT AREAS AFFECTED INCLUDE RECRUITING, RETENTION, PROMOTION, AND TRAINING., ADDITIONALLY, THE ARMY'S CREDIBILITY WITH ITS SOLDIERS WILL SUFFER IF RECLASSIFICATION IS DELAYED.

5. MACOMS ARE REQUESTED TO PROVIDE THE NAME OF THEIR REPRESENTATIVE TO THE USASSC-NCR POC, MR. DON LANE, fautovon 221-42127 NLT 3 NOVEMBER 1433.

UNCLASSIFIED

EG LO X

UUUU qq qq E8 T30

CDR MILPERCEN ALEX VA //DAPC-EPL-T//
CDR FORSCOM FT MCPHERSON GA //AFPR//

UNCLAS

PERSONAL FOR MG O'LEKSY

FROM BG GOURLEY

SUBJECT: PERSONNEL READINESS CONCERNS

- A. UR PERSONAL FOR MSG DTG 190925Z OCT 83 SAB.
- 2. RECOGNIZE AND APPRECIATE THE PERSONNEL READINESS CONCERNS WHICH YOU SURFACED IN YOUR MESSAGE. EACH ISSUE IS BEING CAREFULLY REVIEWED AT THIS TIME BY MY ACTION TYPES AND THOSE AT DMPM AS APPROPRIATE AND IS CURRENTLY SCHEDULED TO BE DISCUSSED AT THE NEXT REGULARLY SCHEDULED PRAC. HOWEVER, I FELT IT NECESSARY TO PROVIDE YOU SOME IMMEDIATE FEEDBACK ON THE CMF &7 DOCUMENTATION AND PERSONNEL FILL ISSUE. I STRONGLY DISAGREE WITH COMPARING THE ON-GOING CMF &7 REVISION WITH THE CMF &3 ACTION. I THINK EACH OF US REALIZES THAT ANY REFERENCE TO CMF &3 IMMEDIATELY RAISES A RED FLAG AND SIGNALS IMMEDIATE FAILURE, WHICH WE HAVE WORKED SO EXTREMELY HARD TO AVOID IN CMF &7 CONVERSION. THEREFORE I TAKE GREAT EXCEPTION TO YOUR COMPARISON IN THIS REGARD.
- LTG ELTON, DCSPER; MG PORTER, DMPM; MG FALTER, CDR, MILPERCEN

CHARLES N. BULLARD, LTC, TC, CH, DAPC-EPL-T 26 0CT 83, 325-8324

WILLIAM H. GOURLEY, BG, UZA, DIR OF ENL PERS, 325-8306

UNCLASSIFIED

K17

E0 50 X

טטטט

COMPLETELY OFF TRACK YET. MY AVIATION BRANCH CHIEF HAS COORDINATED WITH YOUR FORCE DEVELOPERS TO DETERMINE WHERE THE CONCERNS WERE COMING FROM. THE MAJOR PROBLEM APPEARS TO BE HOW TO REQUISITION FILLER PERSONNEL DURING THIS CONVERSION. KEEPING WITH THE APPROVED MILESTONES, REQUISITIONS USING THE NEW DOCUMENTATION WILL NOT BEGIN UNTIL MAY 1984. THEREFORE, YOUR PERSONNEL FOLKS WILL HAVE TO REQUI-SITION AVIATION REPLACEMENTS USING OLD MOS AND AUTHORIZATIONS UNTIL: SUCH TIME AS THE NEW DOCUMENTS ARE APPROVED AND ON OUR SYSTEM. MY PEOPLE WILL CONTINUE TO WORK CLOSELY WITH YOUR STAFF IN THIS AREA. 3. AS AN ITEM OF INTEREST, YOU SHOULD KNOW THAT A COMBINED TEAM FROM FT EUSTIS, VA AND SSC/NCR HAS BEEN REVIEWING CMF 67 REALIGN-MENT DOCUMENTATION FROM THE MACOMS FOR THE PAST MEEK. DURING THIS REVIEW THEY HAVE DETERMINED THAT MOST OF THE DOCUMENTS {ARMY WIDE} CONTAIN PROBLEMS IN AREAS SUCH AS SGA, NEW MOS NOT DOCUMENTED PRO-PERLY, INCORRECT MOS CHOSEN, AND TOTAL AUTHORIZATIONS BEING INCOR-RECT IN MANY CASES. THE CURRENT PROPOSAL IS FOR EACH MACOM TO PRO-VIDE REPRESENTATION AT A REDOCUMENTATION CONFERENCE TO BE CONDUCTED AT DA DURING THE MONTH OF NOVEMBER. THE AFOREMENTIONED REVIEW WAS ANOTHER "SAFETY MEASURE" THAT WAS INCORPORATED INTO THE MILESTONES TO INSURE THAT DOCUMENTATION IS CORRECT PRIOR TO ANY RECLASSIFICATION EO EO X

บบบบ

OF PERSONNEL AND CHANGES IN MTDE/TDA. WITH PROPER INPUT FROM EACH MACOM I AM CONFIDENT WE CAN MAKE THIS CONVERSION A SUCCESSFUL ONE.
4. OUR SOLDIERS ARE THE ARMY.

UNCLASSIFIED

K 19

O IJECT: Redoct entation for CAR to Sectionsification

. .\_\_

E 1,79:

- 1. Our in the period 16-17 coverber 1800, a redocumentation of reference was bundly 600-501 and the M.S. Army Aviation Logistics School, in Sustin, is, with all rejond 100016 in attachment, one of the smaller 100000 such as Jugar, things, and accepted to attern because of and of travel and the small number of Jocusts involved. These model are periodiced by representation than the model of the office of the control of the small number of the model of the control of th
- I. The reason particularly the district was to correct errors in switter data onto this between additional during the dest will indicate and to not those of an an into the saturable of the street, in the last of the last o
- 1. The accesses of the grown memberships agreed by after fixed of the condition of the content of the conten
- 4. It is after an entirement, is an experience of the object of the property of the entire of the

11. 11. 11. 11.

7 20 K

#### DISPOSITION FORM

For use of this form, see AR 340-15, the proponent agency is TAGO.

REFERENCE OR OFFICE SYMBOL

I.APC-EPL-T

Redocumentation of CMF 67 Realignment

COL Eron H LTC Culyas

DAPC-EPL-T

DATE 04 Jan 84


LTC Bullard/jh/58324


1. Sir Per Coordination with Mr Don Lane, SSC-NCR, the changes that were submitted by the field in regards to the CMF 67 Realignment and reclassification effort cannot be re-checked until DCSOPS finishes entering all the changes received during the mini-moc vindow that ended 30 November 83. Apparently the changes submitted were more than DCSOPS could handle during the December timeframe. As a result Mr Lane vill ask for a "dump" the end of this week in hopes that the changes are in the system.

2. The representatives from the Aviation Logistics School, Ft Eustis and MILPERCEN are prepared to sit down and review documents when available.

LTC, TC

Chief, Trans/Avn Branch





٠,

The same of the sa



#### DEPARTMENT OF THE ARMY

US ARMY SOLDIER SUPPORT CENTER
NATIONAL CAPITAL REGION
200 STOVALL STREET
ALEXANDRIA, VIRGINIA 22332

14 FEB 1984

SUBJECT: Trip Report (USAREUR, 29 January-5 February 1984)

SEE DISTRIBUTION

1. A documentation assistance team, sponsored by the SSC-NCR, visited HQ USAREUR during the period 26 January-5 February 1984. The following personnel constituted the team:

Mr. Donald Lane, SSC-NCR, AV 221-0411/9212 CW4 Aleck Fletcher, SSC-NCR, AV 221-9400/9401 Mr. Robert Wittke, USASC&S, AV 780-6850/7360

- 2. The purpose of the visit was to assist HQ USAREUR to document changes incurred as the result of the restructure of CMF 67, CMF 63 (MUS 638, 520, 520 and 52F) and CMF 31 (05B, 05C, 36K to 31C, 31K and other MOS). An additional purpose was to obtain insight into the systemic problems which had caused problems in the documentation of the changes in CMF 67 and the PGE portion of CAF 53.
- Visits were made to four distinct areas with HQ JSAREUR/1st PERSCOM. The areas visited were:

SECTION	PRIMARY POC	ISSUE
CINCUSAREUR	General Otis	Purpose/results of visit in terms of LIG Elton's Message.
HQ JSAREUR, DCSRM	LTC Nowlin/SFC Sudberry	Documentation assistance.
HQ USAREUR, DCSPER	MAJ Melton/MAJ Mortensen	Courtesy visit/ASI Maintenance/Processing Time.
1st PERSCOM	COL Vollrath/MAJ Traub	Personnel Reclassifica- tion/Management Issues

Additional personnel were consulted in each of these areas. The names of the specific personnel, other than those above, are included as appropriate within the attached "issue sheets."

122

1.14

ATZI-NCO-SC

SUBJECT: Trip Report (USAREUR, 29 January-5 February 1984)

4. The team was treated with courtesy and respect by all whom we met. Inis made our work easier and helped us to convey our thoughts to the USAREUR personnel in the various sections we visited. Special thanks are due to MSG Sudberry, DCSRM, and MSG Crosby, 1st PERSCOM, for the assistance they and their personnel gave our team.

1 Enclosure as

DONALD F. LANE Military Occupational Management Specialist Team Leader

DISTRIBUTION:
CINCUSAREUR (AGAGF-ADE)
CDR, 1st PERSCOM (AEUPE-EPMD)
CDR, USAMILPERCEN (DAPC-EPL-T)
CDR, USAMILPERCEN (DAPC-PLO)
CDR, USAMILPERCEN (DAPC-EPL-O)
CDR, USAMILPERCEN (DAPC-EPL-O)
COL POPOVICH, PRAD
MAJ LAROUCHE, PRAD
MAJ PRICE, PRAD
LTC MILLER, PCC

1 4 1

#### ISSUE 1. DOCUMENTATION OF OMF 67 RESTRUCTURE

1. Background. This issue developed during October 1983 after a review of documents which contain the requirements/authorizations for OTF 67 determined that major documentation deficiencies had occurred during the July-September 1983 MOC Window. This condition was not unique to USAREUR, but had occurred across the entire Army. As a result, a redocumentation conference was held in Alexandria, Virginia, 14-17 November 1983, to attempt to correct the problems in the Mini-MOC Window for November 1983. USAREUR did not submit corrections/changes within the Mini-MOC Window.

#### 2. Facts Bearing on the Problem.

- a. MOS Decision was made by the HQDA DCSPER on 20 December 1982.
- b. LON was published on 13 January 1983.
- c. CCT 300-74 contained, essentially, all the changes necessary to properly update MTOE units with the CMF 67 restructure. These were not applied by USAREUR because of HQDA DCSOPS guidance to the field regarding implementation. Subsequent guidance by HQDA DCSOPS to document administrative changes was not clear and was not understood by HQ USAREUR documentation personnel.
- d. A scrub, January 1984, revealed the same errors in USAREUR documents as were previously noted in October 1983 for CAF 67. SFC Pompa, USAREUR, DCSRM, confirmed that corrections had not been submitted due to time limitations.

#### 3. Findings.

- a. The input for MTOE for Jan-Mar 84 MOC Window was reviewed by Mr. Lane on 29 Jan-5 Feb 84. Of the documents checked in detail (approximately 25), none contained errors of the type previously noted for QMF 67. Other errors in these documents in PGE and Signal areas were noted in some instances. In some cases for QMF 67, the position titles were erroneous.
- b. The TDA's were discussed with Mr. Litvinias. TDA procedures are different insofar as application of changes of the structure affect them. No documents were available for review, but Mr. Lane provided the Branch Chief with the specific changes, by paragraph and line number, to effectively implement the changes in CMF 67 to all the affected TDA's in USAREUR.

#### 4. Recommendation.

a. That USAREUR place considerable emphasis on applying their input to their MTOEs and ensure transmission of this information to HQDA TAADS via the VTAADS.

- b. That USAREUR ensure that the input provided them by SSC-NCR be applied to applicable TDA's to complete their documentation.
- c. That SSC-NCR, once again, scrub the USAREUR documents in April 1983 to verify the results of this documentation effort.

K 25

# ISSUE 2. DOCUMENTATION OF 63B - WHEEL VEHICLE MECHANIC AND 52D - POWER GENERATION EQUIPMENT MECHANIC

1. Background. This issue developed doing October 1983 after a review of documents, which contained requirements/authorizations for MOS 63B/52D soldiers, determined that major deficiencies in the documentation of the proposed MOS split existed. As a result of the problems in CMF 63 and 67, a conference was held in Alexandria, Virginia, 14-18 November 1983, to correct the problems and provide guidance for the documentation; however emphasis was on CMF 67.

#### 2. Facts Bearing on the Problem.

- a. MOS decision was made in December 1982.
- b. LON was published and amended in January 1983.
- c. CCT 300-74 contained many errors which affected the documentation of the PGE changes. While some of these changes were selectively applied to documents, the errors/omissions in CCT 300-74 were also carried over to the affected MTOE's. CTU 83-10 corrected most of these problems and documents posted from CTU 83-10 will be, for the most part, accurate.
- d. Since the PGE changes were to be posted to the VTAADS in October 1983, there are no "systems identified" transactions or suspenses currently being generated by the VTAADS. The result is that PGE changes must now be made by a total and manual scrub of the affected MTOE/TDA documents to compare CTU 83-10 and the unit document.

#### 3. Findings.

- a. The input for the Jan-Mar 84 MOC Window was reviewed by CW4 Fletcher on 29 Jan-2 Feb 84. The documents checked in detail contained errors of the same magnitude as discovered in the SSC-NCR scrubs of the CMF 63 documents in November 1983.
- b. Majority of the errors were recognized by a detailed scrub of the Consolidated TOE Update (CTU) 8310, against MTOE documents. The various USAREUR SRC action NCO's were loading the corrected documentation of 63B/52D split into the data base when the team departed. The documentation effort of the MOS split seems to be on line with published documents and guidance.

#### 4. Recommendation.

That documentation be reviewed by SSC-NCR during April 84 for accuracy.

#### ISSUE 3. ELIMINATION OF MOS 05B (CMF 31)

1. Background. This issue developed from the "Out of Court Settlement" by the Secretary of the Army to eliminate all authorizations for NOS 05B not later than 31 March 1984.

#### 2. Facts Bearing on the Problem.

- a. The proponent (USASC&FG) submitted the 05B proposal as stated in the message in March 1983. (The message was dated 181540Z Feb 83 and the suspense date was 18 March 1983.) The proposal involved hundreds of manhours to be expended and subsequent corrections had to be made because numerous inexperienced personnel were utilized in the preparation of the proposal, which involved the potential reclassification of about 21,000 positions.
- b. Since 05C and 36K positions were involved, SGA's and position titles were also changed.
  - c. The LON was published 6 July 1983.
- d. The doctrinal changes were contained in CTU 83-10 but as a function of its use with USAREUR documents, it was determined that many errors/inaccuracies were contained in the CTU.
- e. The CTU was delayed from 10-83 to 11-83 (USASCAFG impression), but appears to contain some errors in the conversion of these MOSs. MTOEs are now (Feb 84) being updated. The MTOE update must be completed not later than 31 March 1984 but these errors will probably impact on documentation of these changes in MTOE worldwide.
- 3. Findings. The visit (to USAREUR) revealed that the LON and circular were not interpreted as intended and USAREUR was converting 05Bs on a one-for-one basis. This was due to over simplification of the reclassification guidance. The duty position titles were changed and revised SGAs for 05C/3lC and 36K/3lK were included in the proposal. This meant that selective conversions were required, but in some cases USAREUR had interpreted the changes to be one-for-one changes which do not reflect SGA changes.

#### 4. Recommendations.

- a. That conversions of OSC positions be made on a selective basis. While all OSC positions will be converted to 31C, the grades of newly designated 31C positions must be reviewed and may require changes of grade in order to conform to the standards of grade for new MOS 31C announced in LON E-21-21 which are to be incorporated into Change 1, AR 611-201.
- b. That all 05B conversions be made on a selective basis. All MOS 05B positions convert to 31C, 31K or one of several other MOS. The redesignated positions may require regrading to conform with the standards of grades contained in AR 611-201 for the MOS in which redesignated.

KZ7

- c. That all 36K conversions be made on a selective basis. All MOS 36K positions convert to either MOS 31K or selected other MOS. During these conversions, grades of these redesignated positions must be reviewed and may require changes in grade in order to conform to the standards of grades contained in AR 611-201 for the MOS in which redesignated.
- d. That in the conversions of MOS 05B, 05C and 36K to other MOS, care be exercised to ensure that positions are properly retitled to reflect the revised structure contained in AR 611-201 as implemented by DA Circular 611-84-1.

#### ISSUE 4. DOCUMENTATION/MANAGEMENT OF ASI

- 1. Background. USAREUR still appears to have severe problems in documenting and managing personnel by ASI, yet management of personnel by NOS and ASI is essential with Force Modernization. The following USAREUR elements addressed ASI concerns to the team:
  - a. DCSPER, Major Mortensen

b. 1st PERSCOM: Colonel Vollrath

LTC Traub

LTC Spinello; et. al.

c. DCSRM: CPT Fitch

#### 2. Facts Bearing on the Problem.

ASI's are not thoroughly documented in USAREUR documents. There are several apparent reasons for this. Included are:

- (1) It appears that TRADOC may not do an adequate job of documenting ASI in the base TOE and CTUs.
- (2) Many ASIs are equipment oriented; and, there are equipment differences between the base TOE and MTOE.
- (3) ASI descriptions, in many cases, in the opinion of documentation personnel, do not provide adequate detail and description for classification of positions.

#### 3. Findings.

- a. Documentation personnel (at least in USAREUR) depend on the suspense created by the POS Edit File to identify position reclassification actions. There is currently no way to create a suspense document to require coding of positions with an ASI. This can possibly be addressed in a limited way in redevelopment of the POS Edit File to alert documenters that a new ASI has been established for association with specific MOSs.
- b. The MOS system, less ASI's, is a top-to-bottom, imposed system. The ASI is often a bottom-to-top identified requirement. The unit knows first, especially during Force Modernization, what equipment or system is on hand and what additional skills are required of soldiers. Unit Commanders can impact their documents, but they don't know or understand the ASI system in many cases. The result is, more often than not, that ASI requirements go unidentified in documents.
- c. Many soldiers undergo training for an ASI enroute, but arrive in USAREUR without an awarded ASI by the school. Since the training cannot be identified by the USAREUR personnel assignment personnel, the individual is often assigned to another position without consideration being given to the soldier's training for a specific requirement. The net result is the loss of both the training dollars and the soldier's abilities.

KZ9

- d. In some cases it appears that USARFUR MILPOS are awarding ASI's to soldiers without the required training in an effort to meet the ASI requirements in their units. At least one assignments manager in MILPERCEN was quoted as stating that this was the way to solve the problem of the need for ASI qualified personnel.
- e. The USAREUR DCSRM has a history of adding ASI's to their MTOEs, but having the ASI coding questioned by the HQDA DCSPER. Apparently the HQDA DCSPER (DAPE-MPM) used as rationale the need to standardize the MTOE, but that position fails to recognize the role of the ASI in transitioning units during Force Modernization. The ASI application may, necessarily, vary from unit to unit within the same SRC even within the same command. During Force Modernization, it is virtually impossible to standardize the ASI with those found, or not found, in the base TOE. The practice of questioning documents with ASI other than is indicated in a base TOE should be examined by the HQDA DCSPER to allow documentation of ASI requirements unique to a unit's requirements to allow units to base their manpower needs on a realistic document.
- f. The HQDA DCSPER has questioned the use of LIC on documents in USAREUR because addition of an ASI changes the MTOE from a "standard document." USAREUR and other commands have a legitimate and definite need to identify linquist requirements. Linquist requirements cannot be standardized in all Army MTOEs yet they must appear therein as a basis for the Army to identify, access, train and assign language qualified personnel.

## 4. Recommendations.

- a. That the systemic problem with the POS Edit File, as it impacts the documentation of new ASI, be studied and solved as a SSC-NCR/MILPERCEN joint effort.
- b. That a system be established to clearly identify all soldiers scheduled for TDY and ASI training enroute be addressed as a policy issue. Further, a system for awarding the ASI at home station before training, or a similar technique be developed to record the ASI in which to be trained, in records and orders before departure from the losing MILPO. (MILPERCEN effort).
  - c. That other soldiers be awarded ASI only after training is completed.
- d. That there be established a group to study and solve the entire problem of the documenting ASI and LIC to identify unit requirements for uniquely trained personnel with appropriate skills. Further, it is recommended that some type of assistance be given to CINCUSAREUR to resolve this long standing, nagging, and very costly problem.

## ISSUE 5. POSSIBLE OVERAGE OF SIGNAL PERSONNEL

1. Background. As a result of the deletion of 05B from the MOS structure, SSC-NCR issued guidance to the field directing the reclassification of positions to either the predominate MOS in the unit or another "signal" MOS. These conversions will cause a large number of current 05B positions to convert to combat or other non-signal MOS. Even though the redistribution of positions includes non-signal MOS, all current 05B personnel will convert to another signal MOS. The issue is that the conversions of personnel may result in a balloon of personnel in these MOS. For instance, in USAREUR, the concern is that after the six-months substitutability period, these personnel must be absorbed into a signal MOS and they anticipate a significant overage for a period of several months. This situation may be further aggravated by the projected loss of about 2,000 signal spaces during documentation of the "Army of Excellence."

## 2. Facts Bearing on the Problem.

- a. Deletion of 05B from the structure has been mandated for completion in the Jan-Mar 84 MOC Window.
- b. During the six-months conversion period, 05B's will continue to serve in their current position regardless of classification of the position, in order to meet readiness needs.
- c. There is no guidance to substitute "signal people" in the newly created "non-signal" MOS positions subsequent to personnel reclassification scheduled for September 1984.
- d. There will be a significant loss of positions, but there will not be a corresponding reduction in the numbers of personnel.
- 3. Findings. This issue was surfaced by the 1st PERSCOM. They anticipate assignment/utilization problems for current 05B personnel, over the conversions have been made to the new MOS. A secondary problem is that it requires a minimum of 11 months lead time in USAREUR to obtain personnel to fill the newly identified, non-signal authorizations resulting from these conversions.

## 4. Recommendations.

- a. That the scope of this problem, if one exists, be determined Army-wide.
- b. That guidance on utilization of these personnel be issued to assure utilization/readiness considerations for a longer period of time be considered.
- c. That this issue be tasked to MILPERCEN for evaluation of impact on signal enlisted strength and for possible impact on future accessions and/or the training base.

 $K^{31}$ 

## ISSUE 6. SUPPLY OF SUFFICIENT COPIES OF LON'S/STAFFLNG ACTIONS

1. Background. We send only a limited number of copies of LON's and actions for staffing to USAREUR. When our copies arrive, they need to reproduce them in quantity so they can be further staffed and coordinated within USAREUR. Because of severe limitations of local copy equipment, our LON's/actions are sent to a printing plant for reproduction at a cost of 10 or more working days delay.

## 2. Facts Bearing on the Problem.

- a. We provide one copy of actions to be staffed to USAREJR.
- b. We provide two copies of LON's to USAREUR DCSRM and 5 to the 1st Personnel Command.
- c. USAREUR states they need 27 copies of LON's for the 1st PERSCOM and 10 for the DCSRM.

## 3. Findings. N/A

4. Recommendations. That we provide USAREUR with the required numbers of publications to preclude them from the timely reproduction process.

K32

6.1

## ISSUE 7. SUSPENSE DATES

1. Background. USAREUR continues to have a problem meeting some of our suspense dates. They state that they need a minimum of 45 days after arrival of an action in-country for staffing within USAREUR.

## 2. Facts Bearing on the Problem.

- a. USAREUR staffs its actions to Division/local MACOM level within USAREUR.
- b. Local policy requires CINCUSAREUR Chief of Staff approval for expedited action within country.
  - c. Mail time consumes from 8-30 days from the time we mail an action.
- d. Correspondence with an envelope marked "Priority Mail" usually arrives within 8 days of the stated postmark.

## 3. Findings.

- a. One action, subject: Proposed Revision of ASI B8, dated 6 January 1984, arrived in USAREUR on 30 January 1984 with a suspense date of 10 February 1984. The proposed implementation date is 1 March 1985. The envelope was a flat (8-1/2 x 11) mailing, not marked "Priority Mail." USAREUR had to request and was granted a change of suspense to 15 March 1984.
- b. An action, subject: Revision to WO MOS 621 was mailed from here on 25 January 1984; arrived in USAREUR on 2 February. The envelope was marked 'Priority Mail.' The suspense date was 15 March 1985.

## 4. Recommendations.

- a. That all mail we send to USAREUR be marked, or stamped, 'priority mail".
- b. That we standardize our suspense dates for USAREUR approximately 55 days from date of dispatch, whenever staffing parameters permit.

K33

	CRI	TICAL CONVERSIONS	SNC	ERRONEO	ERRONEOUS GRADING	ERRONEOUS	ERRONEOUS DUTY TITLES
МАСОМ	63B-PGE REQMTS	CORRECTLY CODED MOS	ACCURACY	# OF GRA (% OF	# OF GRADING ERRORS (% OF REQMTS)	# OF TITE (% OF I	TITLE ERRORS OF REQMIS)
EUSA	1,197	1,197	100%				
JSAREUR ·	8,226	096"	97%	,		1,472	(18%)
FORSCOM	12,478	12,003	%96	334	(3%)	1,569	(13%)
TRADOC	1,364	1,360	<b>%</b> 66	49	(4%)	107	( 88 )
WESTCOM	793	782	, %66	7.	(%1)	370	(47%)
DARCOM	124	114	92%		-	4	(33%)
INSCOM	217	217	100%	ო	(1%)	140	(828)
USACC	735	671	91%			298	(40%)
MGW .	17	17	100%				
USARJ	S	ഗ	100%				
SOD/JOINT/OTHER ACTIVITIES	148	147	<b>%</b> 66			က	(22)
HSC	80	~	88%			<b>.</b>	(75%)
005	Ŋ	ഗ	100%		•		
· TOTAL	25,317	24,485	826	393	(2%)	4,075	(16%)
						-	
N							

# SUMMARY OF CHANGES TO DOCUMENTATION FOR CMF 63 POWER GENERATION AUTHORIZATIONS

## MOS Conversions:

Ş	AUTHORIZATIONS	AUTHORIZATIONS MAR 84	IDENTIFIED IN SCRUB	CONVERSIONS	CHANGE
638	22,055	18,183	-811	17,372	1.
520	2,341	5,504	+811	6.315	4 3 974
52C	1,506	1,518	33	, ABE	
52F	0	112	33 6		7

There has been a 709 decrease in total 638/52D authorizations since Dec 82. KELARK:

## . Documentation MOS Accuracy:

Overall documentation accuracy of 63B, 52D, 52C, and 52F positions is estimated at 97% accuracy.

## III. Recommendations:

- That the reclassification of MOS 63B-52D and 52C-52F soldiers commence in July 1984 as scheduled.
  - That the SSC-NCR document assistance team provide the MACOMs with computer runs of CMF 63 positions annotated with recommended position corrections.
- That the proponent conduct a comprehensive MOS review in 1985 of the force structure of MOS 63B, 52D, 52C, and 52F to determine if standards of grade, MOS duty position titles, and other factors need to be modified as a result of the CMF 63 reclassification action of 1983-1984,

11

APPENDIX N

## SUMMARY OF CHANGES TO DOCUMENTATION OF CMF 67 RESTRUCTURE CHANGES

are approximately 60 190 positions currently classified as aeroscouts which still need to be corrected I. MOS CONVERSIONS: While overall, 99 percent of the CMF 67 requirements appear to be correctly coded with the proper MOS, approximately 244 positions still require conversion. These, for the most part, are conversions from a 67-series MOS to a 66-series Technical Inspector MOS. Included to MOS 67V, Aerial Scout Positions.

documents maintained by the DCSPER. The appropriate office had been apprised of the problem and they are acting to correct the joint activity documents. Only four positions remain classified in obsolete 67W.

## I. RECOMMENDATIONS:

That the reclassification of soldiers in CMF 67 commence in July 1984 as scheduled.

ζ-

- That, the SSC-NCR documentation assistance teams provide the MACOMs computer generated extracts annotated with the needed corrections during the scheduled June 1984 visits. 0
- That the proponent perform continuous review of the CMF 67 structure and documentation to ensure optimal effectiveness of the progress made during the past several months.

(May 1984 Document Scrub Results)

		CONVERS	$\cong$	ERRONEOUS	GRADING	REMARKS
MACON	AGG CMF 67 REQR	CODED	TOTAL	# UF EKKONEUUSLY CODED REGMTS	% ERROR	
DCSPER (JT ACTIVITIES)	94	, ,	87%	. 26	57%	Contained four obsolete 67W positions. These documents, in all, one, officer and WO changes for past several cycles have not been updated.
HEALTH SVCS	<u></u>	=	100%	4	36%	Problem with grading of crew chief positions.
CORPS OF ENGR	. 21	12	92%	4	31%	Primary problem is grading of crew chief positions.
USA SAFETY CTR	= 	=	100%		80	•
TOTALS	17,724	17,480	<b>%</b> 66			
	•					GENERAL REMARKS
						1. All commands need to review titles for crew chiefs and eliminate C/E. Crew Engineer is not a proper enlisted title.
						2. Each MACOM should attempt to standardize MTOE documents IAW DA Policy. Currently, documents within a SRC, with different UIC, but with same CCNUM are vastly different in construction, making review difficult.
						3. MACOMS should standardize position titles. There is such a variety, even within the same paragraph, that review is difficult. Use SGA titles in-so-far as possible.
	·					

٠,

CMF 67 RESTRUCTURE (May 1984 Document Scrub Results)

OREA 12  SAREUR 45  FORSCOM 90	AGG CMF C 67 REQR	CORRECTLY	ار ا	C		
٠ •		CODED		# OF ERKONEDUSLI CODED REQMIS	% ERROR	
•	1291	1289	100%		%[	
•	4507	4475	<b>%</b> 66	. 185	84	Many associated omissions/erroneous applica- tion of SQI "F".
*	9038	1588	% 88 65	432	, 34	Many associated omissions/erroneous application of SQI "F". FORSCOM had 133 documents killed which contained many of the needed changes. Crew Chief grading is a problem. Also, when multiple sections are found in a paragraph, grading is being accomplished by total in paragraph, not per separate section.
י וצו וייי וייי וייי	1293	1288	-100%	0	%0	
.estcom	006	006	100%	0	20	
SARCOM 3	315	308	98%	0	%0	
INSCOM	117	113	<b>%</b> 66	ĸ	2%	
COMM CM0	29	69	100%	82	4 96	Communications Command has several positions in 67V titled as "Door Gunners". These are not included as erroneous coding pending review by USARMRDA.
F7.	102	102	100%	4	4 %	•
SAPAH	21	23	100%	0	<b>3</b>	Exceptions to SGA approved by HQDA.

.

W

APPENDIX M

UNCLASSIFIED +

IMPACT ON THE TAADS. INCLUDED ARE OCCUPATIONAL RESTRUCTURING IN CMF 91 (MEDICAL), CMF 33 (INTERCEPT/ELECTRONIC WARFARE), AND CMF 31 (DELETION OF OSH/PEDESIGNATION OF OSC). IN ADDITION THERE ARE OTHER CHANGES OF LESSER SCOPE, BUT NOT IN LESSER IMPORTANCE. WHILE ALL OF THESE DU NOT REQUIRE IMMEDIATE DOCUMENTATION, VERIFICATION OF CHANGES WILL CERTAINLY PRECLUDE SIMILAR DELAYS IN IMPLEMENTATION.

a. MOST OF THE PROBLEMS IN THE TAADS INVOLVE REGRADING OF POSITIONS TO BRING THE GRADE SPREAD INTO LINE WITH APPROVED STANDARDS OF GRADE; RECLASSIFICATION FROM ONE MOS TO ANOTHER ON A ONE-TO-ONE BASIS; OR THE RETITLING OF A POSITION FOR CLEARER IDENTIFICATION. ALL THE CHANGES WILL BE MADE WITHIN THE LEVELS FOR WHICH YOUR UNITS ARE PESOURCED. A FURTHER REVIEW OF DOCUMENTS FOLLOWING THIS MOC WINDOW WILL DETERMINE IF ADDITIONAL DELAY IN SOLDIER

RECLASSIFICATION IS NECESSARY.

JANUARY AND FORSON REGINNING 21 FEBRUARY TO BOTH IDENTIFY PROBLEMS IN DOCUMENTING THE PROPER CLASSIFICATION OF POSITIONS. THESE TEAMS HAVE ALSO BEEN DIRECTED TO WORK CLOSELY WITH YOUR DOCUMENTORS TO IDENTIFY THE SYSTEMIC PROBLEMS THAT CAUSE THE ABOVE SITUATION TO CONTINUE TO PLAGUE US.— I ENCOURAGE YOU TO USE THEIR EXPERTISE TO YOUR ADVANTAGE AND PROVIDE US INSITES AS TO HOW WE CAN COLLECTIVELY SOLVE THE PROBLEM. ASSISTANCE FOR OTHER MACOMS IS AVAILABLE, TELEPHONICALLY, FROM THE DEPUTY COMMANDER, USASSC-NCR, AV 221-0411 (POINT OF CONTACT IS MR. DONALD LAME).

6. THINK PEOPLE.

BT #3995

NNNN .

UNCLASSIFIED

PAGE 02 3017122 JAN 64 FIIFADWD/3995 1-2

1

UNCLASSIFIED

CDSN = HDF713 MCN = 84030/12107TOR = 840301708RTTUZYUW RUEADWD3995 0301712-UUUU--YUEAHUF. IZNR UUUUU R 301712Z JAN 84 FM HD DA WASHDC//DAPE-MPM-SS// TO RHCGSRB/CDRUSAFORSCOM FT MCPHERSON GA RUAGAAA/CDRUSAEIGHT SEOUL KOREA RUKLDAR/CDRUSADARCOM ALEXANDRIA VA RUFDAAA/CINCUSAREUR HEIDELBERG GE RUCLAIA/CDRUSATRADOC F.T MONROE, VA RUHHHMA/CDRUSAWESTCOM FT SHAFTER HI RUADJHAZCOR USANJ CP ZANA JAPAN: -INFO RUBAHOF/COR USANILPERCENTALEX VA RUCNAAA/COR USASSCAFT BENJAHIN HARRISON IN RUEAHOF/DEDR USA SSC-NCR ALEKANDRIA VA "BTLESSTERENTION IS NECKSHIE!

٢

UNGLAS AND CAVAZOS, GENERALD, GENERETHE GEN DIESULE GEN RECHARDSON, ILEGILEE LITE, HERAND, MG FALTER, ME FRENCH. COLI BETTINGERISTANIC TRUSTE STATE S SUBJEROBLER AND PROVIDE HE WATTE STE HOW TO CALL COLL COLL STE HOW TO CHE 67 AND CHE 63 EXPONER GENERATION EQUIPMENT ONLY) 4. DUENTONSUBSTANTIAL ERRORS AND ONISSIONS WHICH CONTINUE TO EXIST IN TOE TAADS DESPITE MACON EFORTS TO DOCUMENT CHANGES IN THE MOS STRUCTURE FOR CMF 67 (AVIATION MAINTENANCE) AND CMF 63 (POWER

GENERATION), IT IS NECESARY FOR HODA TO DELAY THE SCHEDULED RECLASSIFICATION OF SOLDIERS IN THE AFFECTED MOS. THIS DELAY WILL BE UNTIL: 1 JULY 1984, AS OPPOSED TO THE PLANNED DATES OF 1 APRIL AND 1 MARCH 1984-RESPECTFULLY.

THESE CHANGES WERE TO BE DOCUMENTED IN THE JULY-SEPTEMBER 1983 MOC WINDOW. AN OCTOBER 1983 DOCUMENT SCRUB REVEALED AN EXCESSIVE ERROR RATE, SO ARRANGEMENTS WERE MADE TO REDOCUMENT DURING THE NOVEMBER 1983 MINI-MOC WINDOW. ANOTHER SCRUB IN JANUARY 1984 REVEALS THAT ONLY TWO SMALL VIAADS PROPONENTS ACHIEVED ACCEPTABLE DOCUMENTATION. WE ARE, AGAIN, IN A MOC WINDON WHICH PROVIDES BOTH TIME AND OPPORTUNITY TO GET OUR TAADS FOR THESE CMF/MOS "STRAIGHT." WE MUST, AT THE END OF THIS MOC WINDOW, HAVE AS OUR GOAL, DOCUMENTS ACCEPTABLE AS A BASIS FOR-ACCESSION, TRAINING

AND PROMOTION OF THE MORE THAN 21,000 SOLDIERS AFFECTED BY THESE CHANGES. I NEED YOUR PERSONAL ATTENTION TO ENSURE THAT THIS GOAL IS ACHIEVED.

DTHER MAJOR CHANGES TO THE MOS STRUCTURE WILL SOON HAVE EQUAL

PAGE 01 UNCLASSIFIED 3017122 JAN 84

APPENDIX L

The second second

ا من جاء ڪئيون ۾ مراس جان

SUBJECT: Procedures for Making Directed Changes to MTOE and TDA.

unit by SRC, UIC, CCNUM, Para, and Line and require submission of such input and tradeoffs where appropriate.

- f. Insure that all such messages include the Office of The Inspector General as an addressee with a request to check on compliance with Para 5c, above.
- Notify US Army, MILPERCEN of the decision so the distribution and requisition validation personnel are aware of the changes to current authorizations.

## ODCSOPS will:

- Adjust PERSACS and FAS as needed.
- Send an updated tape to MACOMs so that changes can be printed and distributed to unit level.
- Review and provide appropriate coordination on all such messages initiated by ODCSPER.
- TOP LOADING OF DECISIONS AT HODA:
- a. When ODCSPER, in coordination with ODCSOPS, determines that a change is of such significance that documentation adjustments cannot wait for establishment methods of feedback through MACOM-generated TAADS action, ODCSPER will top load these changes into TAADS and concurrently advise MILPERCEN for PERSACS computation purposes.
- b. When top loading is required and the changes are of a substantive ' nature (Para 2-2c, AR 310-49), a new TAADS document will be required--see Para ap., Appendix A, AR 310-49. ODCSOPS has the responsibility for managing TAADS documents; therefore, FORDIMS (AS) will permit development of new TAADS documents from the CRTs located in DAMO-FDP, only.

MG WALTER J. MEHL Director of Manpower,

Programs & Budget, ODCSPER

1 2 AUG 1982

BGWG. T. TUTTLE Director of Force Management Directorate, ODCSOPS

1 3 AUG 1982



## DEPARTMENT OF THE ARMY OFFICE OF THE DEPUTY CHIEF OF STAFF FOR PERSONNEL WASHINGTON, DC 20310



REPLY TO

## MEMORANDUM OF UNDERSTANDING BETWEEN THE DEPUTY CHIEF OF STAFF FOR PERSONNEL AND

THE DEPUTY CHIEF OF STAFF FOR OPERATIONS AND PLANS

SUBJECT: Procedures for Making Directed Changes to MTOE and TDA

1. PURPOSE. To establish a management process for expeditiously disseminating directed changes to MTOE and TDA to the appropriate level in the field below the MACCM.

### 2. REFERENCES:

- a. AR 310-49, The Army Authorization Documents System (TAADS), 15 Dec 80.
- b. Letters, HQDA, DAMO-FDP, 13 February and 24 April 1981, Subject: Standardization of MTOE Documentation.
- 3. PROBLEM. Reference 2a, above, limits normal cycle changes to TAADS documentation to the two open MOC windows (1st & 3d Calendar Qtrs). This, in some cases, impairs the timely notification of directed changes to field commanders.
- 4. SCOPE. When a functional review of a Career Management Field identifies a documentation imbalance of such intensity that immediate action must be taken to notify MACOMs and their subordinate elements of decisions made at HQDA, the provisions of this MOU apply.

## 5. ODCSPER will:

- a. Prepare a message to MACOM and other TAADS proponents notifying them of the decision.
- b. Request that MACOM/TAADS proponents disseminate the HQDA decision to the appropriate subordinate unit level.
- c. Include a provision in the message requiring that a copy of it be appended to TAADS documentation at all appropriate levels in the field.
  - d. Top load changes at HQDA subject to the criterion in para 7, below.
  - e. Request input from MACOM when decisions require identification of

K 45

Avn/Trans Branch LTC Baker 18 May 84

## PURPOSE:

To provide data on the conversion of CAF 67.

### FACTS:

- 1. The CNF 67 conversion effort expands CNF 67 from 15 MOS to 30 MOS and identifies a soldiers skill to a particular aircraft system. Approximately 3200 soldiers are affected by the conversion.
- 2. The CHF 67 conversion originally scheduled for 1 Oct 83, was delayed until 1 Jul 64 primarily due to installation errors in the VTAADS authorization documents.
- 3. At present, approximately 99 percent of the CMF 67 requirement documents are correctly coded with the proper MOS. Only about 60 19D positions remain to be coded to 67V and 184 67 series MOS remain to be converted to the 66 series Technical Inspector MOS. Remaining problems appear minor and should be easily corrected during the July September MOC window.
- 4. The training of soldiers converting into the 66 series Technical Inspector MCG at Ft Eastis is proceeding as scheduled.
- 5. Delaying implementation would result in field units continuing to receive soldiers who lack the required aircraft particular expertise. MILPERCEN management and distribution would also be hampered.
- 6. Due to confusion in the field, some installations have already cut orders and loaded the new MOS into the SIDPERS. They are now requisitioning based upon the new MOS. As a result, transactions will not consumate and must be handled manually.
- 7. SSC-NCR and all personnel in the Avn/Trans Branch feel very strongly that the 1 July implementation date for the CMF 67 conversion is realistic and in the best interest of both the field units and MILPERCEN.

MARVIN H. BAKER LTC, AV Avn/Trans Branch

K45

## 

use of this form, see AR 340.15, the proponent agency is TAGO. SUBJECT FERENCE OR OFFICE SYMBOL Results of DMF 67 and 62-PGE Document Review '.TZ I-HCO-SC

FROM

DATE

CMT 1

DAPC-PLO .

ATZ I -NCO

Mr. Lane/c1/325-0411

14 MAY 1984

- 1. SSC-NCR has completed its review of documents to determine the current status of MACON documentation of CNF 67 and CMF 63 power generation equipment (PGE) positions. Overall, the documents show significant improvement over earlier documentation and fully supports the need to "press on" with the personnel reclassification process. Detailed data concerning the results of the review are shown in the attached inclosures.
- Some minor documentation problems were noted during the document review process and should be corrected by the MACOMs during the next MOC window (July-September 1984):
- a. In both USAREUR and FORSCOM, several positions now classified in the 67 series MOS need to be converted to a 66-series Technical Inspector MOS. In FORSCOM, several Aerial Scout positions remain classified in MOS 19D. In nearly all commands, some corrections to SGA applications are required.
- b. In the area of Power Generation Equipment (PGE), approximately 811 (4% of the total MOS 632 requirements) still need to be converted to 52D. Approximately 16% of the duty position titles still contain reference to PGE. Within USAREUR, fewer MOS 52F positions have been identified than anticipated to support projected equipment requirements.
- c. FORSOOM "killed" 133 documents for various reasons during the last MOC window and, therefore, the intended changes are not reflected in the SSC-NCR review.
- 3. In June, SSC-NCR is dispatching documentation assistance personnel to the MACOMs. Recommended position change information, in SRC/UIC/paragraph/line number detail, will be provided to the MACOMs during the visits which will permit the MACOMs to correct the remaining minor problems discussed above during the July-September MOC window.
- 4. As a result of the significant improvement in MACOM documentation of CMFs 67 and 63 during the past three MOC windows, and the minor documentation corrections which the MACOES will perform in the next MOC window, recommend that the reclassification of personnel in TAF 67 and the PGE portion of CAF 63 be directed for action by the MILPOs during July 1984.

FOR THE DEPUTY COMMANDER:

1 Incl 2 E

DENNIS D. FLIKT

Colonel, @

Director, Military Occupational

Development

DAPE SIPH

KUY

